

THIS SERVICE RECORD shall accompany the propeller equipment at all times. When equipment is installed as part of an Aircraft or engine, this record shall be maintained concurrently with and become a part of the Aircraft and Engine Service Records.

PROPELLER MAINTENANCE RECORD

Position single

PITCH RANGE

Propeller Model PHC-53YE-1RF

High/Feather _____

Propeller S/N FP 1872B

Start Lock _____

Blade Design _____

Low _____

Blade S/N's

Reverse _____

No. 1 J 76898

No. 2 J 76900

Aircraft Manufacturer # Cirrus

No. 3 J 76901

Aircraft Model SR 22

No. 4 _____

S/N 0327

No. 5 _____

Registration N877CD

No. 6 _____

Spinner Assembly Part No. _____

DLK 2601 Cessna Lane Kennesaw, GA 30144 770-427-4954
LOG ID# 4177 26-August-2003 REF# 3359
N877CD S/N 0327 CIRRUS SR22
HOBBS 475.4
TTPROP 475.4
AVIATION, INC. Pg 1 / 1

*** PROPELLER LOG BOOK ***

SEE AIRCRAFT LOG FOR AD'S COMPLIED WITH DURING THIS ANNUAL. DRESSED AND PAINTED PROPELLERS.

I CERTIFY THAT THIS AIRCRAFT AND/OR ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH A/AN ANNUAL INSPECTION AND DETERMINED TO BE IN AIRWORTHY CONDITION.

Daniel L Kendall
Signed DK7R795J FOR DLK AVIATION, INC.

DLK 2601 Cessna Lane Kennesaw, GA 30144 770-427-4954
LOG ID# 5623 02-September-2004 WO# 4480 REF# 4480
N877CD S/N 0327 CIRRUS SR22
HOBBS 671.1
TTPROP 671.1
AVIATION, INC. Pg 1 / 1

*** PROPELLER LOG BOOK ***

SEE AIRCRAFT LOG FOR AD'S COMPLIED WITH DURING THIS ANNUAL. DRESSED AND PAINTED PROPELLERS.

I CERTIFY THAT THIS AIRCRAFT AND/OR ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH A/AN ANNUAL INSPECTION AND DETERMINED TO BE IN AIRWORTHY CONDITION.

Daniel L Kendall
Signed DK7R795J FOR DLK AVIATION, INC.

DLK 2601 Cessna Lane Kennesaw, GA 30144 770-427-4954
LOG ID# 6423 18-May-2005 WO# 5266
N877CD S/N 0327 CIRRUS SR22
HOBBS 769.8
TTPROP 769.8
AVIATION, INC. Pg 1 / 1

*** PROPELLER LOG BOOK ***

SEE AIRCRAFT LOG FOR AD'S COMPLIED WITH DURING THIS ANNUAL. DRESSED AND PAINTED PROPELLERS.

I CERTIFY THAT THIS AIRCRAFT AND/OR ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH A/AN ANNUAL INSPECTION AND DETERMINED TO BE IN AIRWORTHY CONDITION.

Daniel L Kendall
Signed DK7R795J FOR DLK AVIATION, INC.

Date	Propeller		A/C	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO	Hrs	



2601 Cessna Lane Kennesaw, GA 30144 770-427-4954
 LOG ID# 7671 17-May-2006 WO# 6247
 N877CD S/N 0327 CIRRUS SR22
 HOBBS 913.3
 TTPROP 913.3


Pg 1 / 1

*** PROPELLER LOG BOOK ***

SEE AIRCRAFT LOG FOR AD'S COMPLIED WITH DURING THIS ANNUAL. DRESSED AND PAINTED PROPELLERS. I CERTIFY THAT THIS AIRCRAFT AND/OR ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH A/AN ANNUAL INSPECTION AND DETERMINED TO BE IN AIRWORTHY CONDITION.

MAINTENANCE RELEASE.
 THIS AIRCRAFT, AIRFRAME, AIRCRAFT ENGINE, OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT MAINTENANCE RULES OF THE FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE FOR WORK PERFORMED UNDER WO#6247 AT REPAIR STATION DK7R795J. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION.

Donald C. Kendall
 Signed DK7R795J FOR DLK AVIATION, INC.



Date	Propeller	Work Order:	

Complied with ANNUAL inspection I/A/W Cirrus SR22 M.M. 5-20 and 5-30.
 This Propeller has been inspected I/A/W ANNUAL inspection and has been determined to be in airworthy condition. Propeller return to service.-----END-----

The aircraft, engine, propeller, or appliance identified above was repaired and/or inspected in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details are on file at this agency under work order # RM-000997 & RM-000998

Authorized Signature *[Signature]*
 The Hangar Inc. CRS # 1041557
 2930 Winchester Road, Suite 500 Memphis, TN 38118

DLK

2601 Cessna Lane Kennesaw, GA 30144 770-427-4954
LOG ID# 10238 20-March-2008 WO# 8146
N877CD S/N 0327 CIRRUS SR22
HOBBS 1138.4
TTPROP 1138.4

AVIATION, INC.

*** PROPELLER LOG BOOK ***

SEE AIRCRAFT LOG FOR AD'S COMPLIED WITH DURING THIS ANNUAL. DRESSED PROPELLERS. I CERTIFY THAT THIS AIRCRAFT AND/OR ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH A/AN ANNUAL INSPECTION AND DETERMINED TO BE IN AIRWORTHY CONDITION.

MAINTENANCE RELEASE.

THIS AIRCRAFT, AIRFRAME, AIRCRAFT ENGINE, OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT MAINTENANCE RULES OF THE FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE FOR WORK PERFORMED UNDER WO#8146 AT REPAIR STATION DK7R795J. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION.

Donald L. Kendall
Signed DK7R795J FOR DLK AVIATION, INC.

DLK

2601 Cessna Lane Kennesaw, GA 30144 770-427-4954
LOG ID# 11389 12-March-2009 WO# 9099
N877CD S/N 0327 CIRRUS SR22
HOBBS 1202.9
TTPROP 1202.9

AVIATION, INC.

*** PROPELLER LOG BOOK ***

SEE AIRCRAFT LOG FOR AD'S COMPLIED WITH DURING THIS ANNUAL. DRESSED PROPELLERS. I CERTIFY THAT THIS AIRCRAFT AND/OR ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH A/AN ANNUAL INSPECTION AND DETERMINED TO BE IN AIRWORTHY CONDITION.

MAINTENANCE RELEASE.

THIS AIRCRAFT, AIRFRAME, AIRCRAFT ENGINE, OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT MAINTENANCE RULES OF THE FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE FOR WORK PERFORMED UNDER WO#9099 AT REPAIR STATION DK7R795J. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION.

Donald L. Kendall
Signed DK7R795J

N877CD
Hobbs: 1275.5
TSPOH: 1275.5
04/02/10

Dressed blades. Balanced Propeller to engine .038ips.

I certify that this Propeller has been inspected in accordance with An Annual inspection and was determined to be in an airworthy condition.

Rushing Aviation
703 Airport Rd.
Marks, MS 38646

Karin Rushing
1A425136265


Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		

N877CD
Hobbs: 1377.6
TSPDH: 1377.6
04/22/11

Dressed blades.

I certify that this Propeller has been inspected in accordance with
An Annual inspection and was determined to be in an airworthy condition.

Rushing Aviation
703 Airport Rd.
Marks, MS 38646


Kevin Rushing

17425436265

N877CD
Tach: 1419.9
TSPDH: 1419.9
04/06/12

Dressed Blades

I certify that this Propeller has been inspected in accordance with
An Annual Inspection and was determined to be in an airworthy condition.

Rushing Aviation
703 Airport Rd.
Marks, MS 38646


Kevin Rushing

IA3412822

N877CD
Tach: 1486.2
TSN: 1486.2
05/01/13

Dressed Blades

I certify that this Propeller has been inspected in accordance with
An Annual Inspection and was determined to be in an airworthy condition.

Rushing Aviation
703 Airport Rd.
Marks, MS 38646



Kevin Rushing

IA3412822


Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
				N877CD Tach: 1545.6 TSN: 1545.6 04/16/14 Dressed Blades I certify that this Propeller has been inspected in accordance with An Annual Inspection and was determined to be in an airworthy condition. Rushing Aviation 703 Airport Rd. Marks, MS 38646 Kevin Rushing IA3412822

				N877CD Tach: 1600.0 TSN: 1600.0 04/28/15 Dressed Blades I certify that this Propeller has been inspected in accordance with An Annual Inspection and was determined to be in an airworthy condition. Rushing Aviation 703 Airport Rd. Marks, MS 38646 Kevin Rushing IA3412822

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
			N877CD Tach: 1691.4 TSN: 1691.40 04/27/17	
			Dressed Blades	
			I certify that this Propeller has been inspected in accordance with An Annual Inspection and was determined to be in an airworthy condition.	
			Rushing Aviation 703 Airport Rd. Marks, MS 38646	Kevin Rushing IA3412822
			N877CD Tach: 1737.9 TSN: 1737.9 04/18/18	
			Dressed Blades	
			I certify that this Propeller has been inspected in accordance with An Annual Inspection and was determined to be in an airworthy condition.	
			Rushing Aviation 703 Airport Rd. Marks, MS 38646	Kevin Rushing IA3412822

			N877CD Tach: 1786.4 TSN: 1786.4 04/09/19	
			Dressed Blades	
			I certify that this Propeller has been inspected in accordance with An Annual Inspection and was determined to be in an airworthy condition.	
			Rushing Aviation 703 Airport Rd. Marks, MS 38646	Kevin Rushing IA3412822
			N877CD Tach: 1818.2 TSN: 1818.2 04/24/20	
			Dressed Blades	
			I certify that this Propeller has been inspected in accordance with An Annual Inspection and was determined to be in an airworthy condition.	
			Rushing Aviation 703 Airport Rd. Marks, MS 38646	Kevin Rushing IA3412822

Date	Propel TSN	Description of all operations pertaining to Airworthiness Directives, specifications.
	N877CD Tach: 1865.5 TSN: 1865.5 05/03/21	Dressed Blades I certify that this Propeller has been inspected in accordance with An Annual Inspection and was determined to be in an airworthy condition. Rushing Aviation 703 Airport Rd. Marks, MS 38646
		 Kevin Rushing IA3412822
	N877CD Tach: 1903.5 TSN: 1903.5 05/18/22	Dressed Blades I certify that this Propeller has been inspected in accordance with An Annual Inspection and was determined to be in an airworthy condition.
		 Kevin Rushing IA3412822

	N877CD Tach: 1927.1 TSN: 1927.1 05/18/23	Dressed Blades I certify that this Propeller has been inspected in accordance with An Annual Inspection and was determined to be in an airworthy condition.
		 Kevin Rushing IA3412822