

**PROP**

**LOGS**

**HARTZELL PROPELLER INC**  
INSPECTION

Item Number: J3F30500AFM

Date: 2/8/2012

Work Order #: M488360

Model Number PHC-J3Y1F-1N/N7605B											
Ass'y Ser No. NJ568B		Hydr Unit No. NA		Bulkhead No. NA			Valve No. NA				
Blade 1: A5587		Blade 2: A5586		Blade 3: A5591		Blade 4:		Blade 5:		Blade 6:	
Clamp 1:		Clamp 2:		Clamp 3:		Clamp 4:		Clamp 5:			
Reverse NA	Start Lock NA	Low Pitch 12.2	High Pitch 35.0	Feather NA	Position 3	Orient. L	Qty:Al 1	St 0	Scrw 0	A-2424-1 0	Washer 2
Ref Radius (inches) for angles: 30											
Comments: Deice Kit: NA											
Packing Certified By: <i>John Martin</i>				Date: 2-8-12							
Inspected By: John Martin											

The approved design data for this propeller incorporates all changes required by applicable Airworthiness Directives.

THIS SERVICE RECORD shall accompany the propeller equipment at all times. When equipment is installed as part of an Aircraft or engine, this record shall be maintained concurrently with and become a part of the Aircraft and Engine Service Records.

### PROPELLER MAINTENANCE RECORD

Position <u>FRONT</u>	PITCH RANGE
Propeller Model <u>PHC-J3Y1F-1N</u>	High/Feather <u>35.0</u>
Propeller S/N <u>NJ568B</u>	Start Lock <u>N/A</u>
Blade Design <u>N7605B</u>	Low <u>12.2</u>
Blade S/N's	Reverse <u>N/A</u>
No. 1 <u>A5587</u>	Aircraft Manufacturer <u>CIRRUS</u>
No. 2 <u>A5586</u>	Aircraft Model <u>SR22</u>
No. 3 <u>A5591</u>	S/N <u>1493</u>
No. 4 _____	Registration <u>NPS100</u>
No. 5 _____	
No. 6 _____	
Spinner Assembly Part No. _____	



PROP MODEL:  
PHC-J3Y1F-1N/N7605B  
PROP S/N: NJ568B  
REG. NO: N851CD  
WORK ORDER: 27747



## American Aircraft Maintenance, Inc.

Repair Station No. Z5SR421Y  
19711-B Campus Drive  
Santa Ana, CA 92707  
Phone: (949) 852-8420

DATE: 11/13/2015  
A/C TSN: 2734.6  
PROP TT: 486.6  
HOBBS: 2734.6

### Prop Entries

Complied with an Annual/100 HR inspection in accordance with FAR Part 43, Appendix D, using Cirrus Airplane Maintenance Manual Model SR22 section 05-20 as a guide. Leak check satisfactory. All Airworthiness Directives are in compliance at this time through bi-weekly issue 2015-22.

---

THIS AIRCRAFT OR COMPONENT HAS BEEN REPAIRED AND/OR INSPECTED AS OUTLINED ABOVE IN ACCORDANCE WITH CURRENT MAINTENANCE RULES OF 14 CFR, IT IS FOUND AIRWORTHY AND IS APPROVED RETURN TO SERVICE.

DATE: 11/13/2015

SIGNED:

Richard Sanchez  
Certified Repair Station No. Z5SR421Y

Work Order: 27747

Printed by EBis 3 (datcomedia.com)

PROP MODEL:  
PHC-J3Y1F-1N/N7605B  
PROP S/N: NJ568B  
REG. NO: N851CD  
WORK ORDER: 28297

## American Aircraft Maintenance, Inc.

Repair Station No. Z5SR421Y  
19711-B Campus Drive  
Santa Ana, CA 92707  
Phone: (949) 852-8420

DATE: 12/21/2016  
A/C TSN: 2798.8  
PROP TT: 550.8  
HOBBS: 2798.8

### Prop Entries

Complied with an Annual/100 HR Inspection in accordance with FAR Part 43, Appendix D, using Cirrus Airplane Maintenance Manual Model SR22 section 05-20 as a guide. All Airworthiness Directives are in compliance at this time through bi-weekly issue 2016-25.

---

THIS AIRCRAFT OR COMPONENT HAS BEEN REPAIRED AND/OR INSPECTED AS OUTLINED ABOVE IN ACCORDANCE WITH CURRENT MAINTENANCE RULES OF 14 CFR, IT IS FOUND AIRWORTHY AND IS APPROVED RETURN TO SERVICE WITH RESPECT TO THE WORK PERFORMED.

DATE: 12/21/2016

SIGNED:



Michael Rogers  
Certified Repair Station No. Z5SR421Y

Work Order: 28297

Printed by EBis 3 (datcomedia.com)

PROP MODEL  
PHC-J3Y1F-1N/N7605B  
PROP S/N NJ568B  
REG NO N851CD  
WORK ORDER 17-1522



## American Aircraft Maintenance, Inc.

Repair Station No. Z5SR421Y  
19711-B Campus Drive  
Santa Ana, CA 92707  
Phone: (949) 852-8420

DATE: 1/17/2018  
A/C TSN: 2889 6  
PROP TT: 641 6  
HOBBS: 2889 6

### Prop Entries

Complied with an Annual inspection in accordance with FAR Part 43, Appendix D, using Cirrus Airplane Maintenance Manual Model SR22 section 05-20 as a guide. All Airworthiness Directives are in compliance at this time through bi-weekly issue 2017-25. ... Feathered nick at face of prop blade. Primed and painted area.

---

THIS AIRCRAFT OR COMPONENT HAS BEEN REPAIRED AND/OR INSPECTED AS OUTLINED ABOVE IN ACCORDANCE WITH CURRENT MAINTENANCE RULES OF 14 CFR, IT IS FOUND AIRWORTHY AND IS APPROVED RETURN TO SERVICE WITH RESPECT TO THE WORK PERFORMED

DATE: 1/17/2018

SIGNED:

A handwritten signature in black ink, appearing to read 'Ysmael Galera', written over a horizontal line.

Ysmael Galera  
Certified Repair Station No. Z5SR421Y

Work Order: 17-1522

Printed by EBis 3 (datcomedia.com)

PROP MODEL:  
PHC-J3Y1F-1N/N7605B  
PROP S/N: NJ568B  
REG. NO: N851CD  
WORK ORDER: 17-2048



## American Aircraft Maintenance, Inc.

Repair Station No. Z5SR421Y  
19711-B Campus Drive  
Santa Ana, CA 92707  
Phone: (949) 852-8420

DATE: 2/12/2019  
A/C TSN: 2972  
PROP TT: 724  
TSPOH: 724  
HOBBS: 2972

### Prop Entries

Complied with an Annual inspection in accordance with FAR Part 43, Appendix D, using Cirrus Airplane Maintenance Manual Model SR22 section 05-20 as a guide. All Airworthiness Directives have been researched through bi-weekly issue 2019-01.... Dressed propeller and re-painted blades face.

---

I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION AND APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE WORK PERFORMEND ARE ON FILE AT THIS FACILITY.

DATE: 2/12/2019

SIGNED:

A handwritten signature in black ink, appearing to read 'Y Galera', written over a horizontal line.

Ysmael Galera  
Certified Repair Station No. Z5SR421Y

Work Order: 17-2048

Printed by EBis 3 (datcomedia.com)



MODEL SR22  
S/N 1493  
REG. NO. N851CD  
PROP MOD \_\_\_\_\_  
PROP S/N \_\_\_\_\_



**MATHER**  
**AVIATION**

818-782-7473

7240 HAYVENHURST PLACE

VAN NUYS, CALIFORNIA 91406

**PROPELLER LOGBOOK INSERT**

DATE 17-Mar-20  
W.O. # 804307  
HOBBS. 3016.7  
PROP TSO \_\_\_\_\_  
PROP TSN \_\_\_\_\_

- 1 Complied with an annual inspection
- 2 12 month propeller lubrication

I certify this aircraft/engine/propeller has been inspected IAW current Federal Aviation Regulations part 43 appendix "D" (annual or 100 hour) inspection. Only the items specified in the Shop Order have been inspected and found to be Airworthy and Returned to Service. No other representations concerning Airworthiness are expressed or implied.

William P Noctor  
Signature

CRS# 1MER830B  
CERTIFICATE #

17-Mar-20  
Date



**MATHER  
AVIATION**

818-782-7473

7240 HAYVENHURST PLACE

VAN NUYS, CALIFORNIA 91406

**PROPELLER LOGBOOK INSERT**

MODEL SR22  
S/N 1493  
REG. NO. N851CD  
PROP MOD \_\_\_\_\_  
PROP S/N \_\_\_\_\_

DATE 2-Aug-21  
W.O. # 804755  
FLIGHT 3071.8  
PROP TSO \_\_\_\_\_  
PROP TSN \_\_\_\_\_

- 1 Complied with an annual inspection
- 2 12 month propeller lubrication

I certify this aircraft/engine/propeller has been inspected IAW current Federal Aviation Regulations part 43 appendix "D" (annual or 100 hour) inspection. Only the items specified in the Shop Order have been inspected and found to be Airworthy and Returned to Service. No other representations concerning Airworthiness are expressed or implied.

*Nicholas Martin*

Signature

CRS# 1MER830B

CERTIFICATE #

2-Aug-21

Date