



Cessna

A Textron Company


## PROPELLER MAINTENANCE RECORD

AIRCRAFT SERIAL AND REGISTRATION 18281497 N165887/262CL

PROPELLER MODEL AND SERIAL B3D36C431/80 VSA-1

HUB SERIAL 041928 BLADE SERIALS PT26163, PT26165, PT26166

### MAINTENANCE RECORD

DATE	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10ths		
2004 12/14	4	6	Propeller hub S/N <u>041928</u> , blade S/N <u>YJ26163</u> , S/N <u>YJ26165</u> and S/N <u>YJ26166</u> has been installed on engine S/N <u>L-29920-48A</u> on aircraft <u>18281497</u> .	  ODARF100129CE

**West Valley Flying Club**

Date: 02/04/05      ACTT: 48      TACH: 48

Inspected propeller IAW Cessna 182T MM 50 hr. checklist

**This propeller is airworthy.**

Charles Haskins A&P 2742590.



12, the work identified in  
shed in

21/1/05

### MAINTENANCE RECORD

DATE 19__	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10ths		
			<p><u>Trade Winds Aviation 2505 Cunningham Ave San Jose CA</u>  May 6, 2005 103 Tach / TTAF N262CL</p> <p>Dressed small nicks on blade leading edges. Removed and installed spinner dome for inspection. I certify this propeller has been inspected in accordance with a 100hr inspection, 14CFR 43 appendix D, and was determined to be in airworthy condition.</p> <p><u>Thomas Nicholson A&amp;P 2522802</u></p>	



DATE	TOTAL TIME IN SERVICE	
19	HOURS	10ths

DESCRIPTION OF THE WORK PERFORMED

AUTHORIZED SIGNATURE,  
CERTIFICATE TYPE  
& NUMBER


***West Valley Flying Club***

**DATE: 06-02-05 ACTT:124 TACH: 124**

Inspected propeller using Cessna 182 50hr MM checklist as a guide.

This propeller is airworthy.

Annette Stichel A&P606981190



***West Valley Flying Club***

**DATE: 08/05/05 ACTT:199 TACH:199 ETSMO:199**

Inspected prop using Cessna 182 100hr MM checklist as guide. This propeller airworthy

FEROZ KHAN A&P 604158361



**West Valley Flying Club**

DATE: 09/23/05 ACTT:245 TACH:245

Inspected propeller using Cessna 182 MM 50 hr. checklist as a guide. This propeller is returned to service.  
A&P 2742590



**West Valley Flying Club**

Date:11/17/05 TACH:300 ACTT: 300

Inspected prop using Cessna 182 100HR MM checklist as a guide.  
This propeller is airworthy

FEROZ KHAN A&P 604158361



**West Valley Flying Club**

Date: 11/17/05 Tach: 300 A/CTT: 300  
Completed **Annual Inspection** using the Cessna 182 100hr MM checklist as a guide. This Propeller is Airworthy.  
Kevin Pinger A&P 574543772 IA




**West Valley Flying Club**

1901 Embarcadero Rd. Suite 100  
Palo Alto, CA 94303

DATE: 2/3/2006  
REG #: N262CL  
ACTT: 406  
TACH: 406

COMPLETED <sup>100 Hour AS</sup> ~~50HR~~ INSPECTION USING THE CESSNA 182 <sup>100hr</sup> ~~50HR~~ MM CHECKLIST AS A GUIDE. THIS PROPELLER IS AIRWORTHY.

ANNETTE STICHEL A&P 606981190





1901 Embarcadero Rd. Suite 100  
Palo Alto, CA 94303

DATE: 3/15/2006  
REG #: N262 CL  
ACTT: 447  
TACH: 447

COMPLETED 50HR INSPECTION USING THE CESSNA 182 50HR MM CHECKLIST AS A GUIDE. THIS PROPELLER IS AIRWORTHY.

A. STICHEL A&P 606981190



1901 Embarcadero Rd. Suite 100  
Palo Alto, CA 94303

DATE: 6/6/2006  
REG #: N262CL  
ACTT: 558  
TACH: 558

INSPECTED PROPELLER USING CESSNA 182T 50HR MM CHECKLIST AS A GUIDE. THIS PROPELLER IS AIRWORTHY.

FEROZ KHAN A&P 604158361

Trade Winds Aviation 2505 Cunningham Ave San Jose CA

IN May 5, 2006 500.4 Tach N262CL

- EV 1. Removed and installed spinner dome for inspection.
- 2. Dressed small nicks.
- 3. Touch up paint on aft side of blades.
- 4. I certify this propeller has been inspected in accordance with a 100hr inspection and was determined to be in airworthy condition.

Stephen J Vallentyne A&P 3038691



1901 Embarcadero Rd. Suite 100  
Palo Alto, CA 94303

DATE: 7/10/2006  
REG #: N262CL  
ACTT: 601  
TACH: 601

### INCE RECORD


INSPECTED PROPELLER USING CESSNA 182T MM 100 HR. CHECKLISTAS A GUIDE. THIS PROPELLER IS AIRWORTHY.

*Charles W. H. [Signature]*

WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER

<del>11/11/06</del>	14 AUG 06	Inspected propeller per C182T 50 hr MM checklist as a guide.	as
T=656 TT=656		This propeller is airworthy Mark H. Kurl	
7 sept 06	T=703 TT 703	Inspected propeller using C182T 100 hr MM checklist as a guide. This propeller is airworthy Mark H. Kurl 2734691	
29 sept 06	T=749 TT=749	Inspected propeller using C182 50 hr MM checklist as a guide. This propeller is airworthy.	Mark H. Kurl 2734691

## MAINTENANCE RECORD

DATE	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10ths		
19__			<p><b><u>Trade Winds Aviation 2505 Cunningham Av San Jose CA 95148</u></b></p> <p>N262CL Propeller 11/3/2006</p> <p>Tach / TTPROP: 781.1</p> <p>Dressed small nicks and painted aft face black. I Certify this propeller has been inspected in accordance with an Annual Inspection, was found to be airworthy at this time and is approved for return to service. Nothing Follows---</p>	
			<p></p> <p>Ricardo Martinez, A&amp;P / IA 550730870</p>	


*West Valley*  
**Flying Club**

1901 Embarcadero Rd. Suite 100  
Palo Alto, CA 94303 Tel. 650.856.2030

DATE: 12/29/06  
REG #: 262CL  
ACTT: 829  
TACH: 829

**PROPELLER ENTRY**

COMPLETED 50 HOUR PROPELLER INSPECTION USING CESSNA 182 CHECKLIST AS GUIDE.



PETE KOLENKO A&P 55883476

*West Valley*  
**Flying Club**

1901 Embarcadero Rd. Suite 100  
Palo Alto, CA 94303 Tel. 650.856.2030

DATE: 03/01/2007  
REG #: 262CL  
ACTT: 880  
TACH: 880

**Propeller Entry**

COMPLETED 100 HOUR INSPECTION OF THE PROPELLER USING THE CESSNA 182 MM CHECKLIST AS A GUIDE.



Pete Kolenko A&P 55883476  
MARK KRELING A&P 2734691



# MAINTENANCE RECORD

*West Valley*  
**Flying Club**

1901 Embarcadero Rd. Suite 100  
Palo Alto, CA 94303 Tel. 650.856.2030

DATE: 5/11/2007  
REG #: N262CL  
ACTT 933  
TACH: 933

### Propeller Entry

COMPLETED 50HR INSPECTION USING CESSNA 182 MM CHECK LIST AS A GUIDE.



FEROZ KHAN A&P 604158361

WC

*West Valley*  
**Flying Club**

1901 Embarcadero Rd. Suite 100  
Palo Alto, CA 94303 Tel. 650.856.2030

DATE: 6/19/2007  
REG #: N262CL  
ACTT 984  
TACH: 984

### Propeller Entry

COMPLETED 100 HOUR PROPELLER INSPECTION USING THE CESSNA 182 MAINTENANCE MANUAL CHECK LIST AS A GUIDE.



FEROZ KHAN A&P 604158361

*West Valley*  
**Flying Club**

1901 Embarcadero Rd. Suite 100  
Palo Alto, CA 94303 Tel. 650.856.2030

DATE: 07/16/2007  
REG #: N262CL  
ACTT 1034  
TACH: 1034

### Propeller Entry

COMPLETED 50 HOUR PROPELLER INSPECTION USING CESSNA 182 MAINTENANCE MANUAL CHECK LIST AS A GUIDE.



FEROZ KHAN A&P 604158361


*West Valley*  
**Flying Club**

1901 Embarcadero Rd. Suite 100  
Palo Alto, CA 94303 Tel. 650.856.2030

DATE: 08/29/2007  
REG #: N262CL  
TACH: 1078  
ACTT : 1078

### Propeller Entry

COMPLETED 100 HOUR PROPELLER INSPECTION USING THE CESSNA 182 MM CHECKLIST AS A GUIDE.



PETE KOLENKO A&P 558833476



1901 Embarcadero Rd. Suite 100  
Palo Alto, CA 94303 Tel. 650.856.2030

DATE: 10/15/2007  
REG #: N262 CL  
AFTT: 1130  
TACH: 1130

**Propeller Entry**

COMPLETED 50 HOUR PROPELLER INSPECTION USING THE C-182 MAINTENANCE MANUAL 50 HOUR CHECKLIST AS A GUIDE.

ANNETTE STICHEL A&P 606981190



1901 Embarcadero Rd. Suite 100  
Palo Alto, CA 94303 Tel. 650.856.2030

DATE: 02/25/2008  
REG #: N262CL  
ACTT: 1208  
TACH: 1208

**Propeller Entry**

COMPLETED 50 HOUR PROPELLER INSPECTION USING THE 182 MM 50 HOUR CHECKLIST AS A GUIDE.

JASPER SARDALLA A&P 3287387

Trade Winds Aviation 2505 Cunningham Ave San Jose CA  
December 7, 2007 Tach Time: 1160.4 N262CL

1. Removed and installed spinner dome for inspection.
2. Dressed small nicks from blade leading edges.
3. I certify this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

Thomas Nicholson A&P, IA 2522802




1901 Embarcadero Rd. Suite 100  
Palo Alto, CA 94303 Tel. 650.856.2030

DATE: 4/29/2008  
REG #: N262CL  
ACTT: 1262  
TACH: 1262

**Propeller Entry**

COMPLETED 100 HOUR PROPELLER INSPECTION USING THE CESSNA 182 MM CHECKLIST AS A GUIDE..

JASPER SARDALLA A&P 3287387



1901 Embarcadero Rd. Suite 100  
Palo Alto, CA 94303 Tel. 650.856.2030

DATE: 06/09/08  
REG #: N262CL  
ACTT: 1308  
TACH: 1308

**Propeller Entry**

COMPLETED 100 HOUR PROPELLER INSPECTION USING THE CESSNA 182T MM 100 HOUR CHECKLIST AS A GUIDE.

JASPER SARDALLA A&P 3287387



1901 Embarcadero Rd. Suite 100  
Palo Alto, CA 94303 Tel. 650.856.2030

DATE: 07/01/08  
REG #: 262CL  
ACTT: 1366  
TACH: 1366

**Propeller Entry**

COMPLETED 100 HOUR PROPELLER INSPECTION USING THE CESSNA 182 MM 100 HOUR CHECKLIST AS A GUIDE.

VLADIMIR SHARONOV A&P 3287383



1901 Embarcadero Rd. Suite 100  
Palo Alto, CA 94303 Tel. 650.856.2030

DATE: 08/12/08  
REG #: N262CL  
ACTT: 1416  
TACH: 1416

**Propeller Entry**

COMPLETED 50 HOUR PROPELLER INSPECTION USING THE CESSNA 182 MM 50 HOUR CHECKLIST AS A GUIDE.

JASPER SARDALLA A&P 3287387

*West Valley*  
**Flying Club**


1901 Embarcadero Rd. Suite 100  
Palo Alto, CA 94303 Tel. 650.856.2030

DATE: 09/08/2008  
REG #: 262CL  
ACTT: 1460  
TACH: 1460

**J COM**  
**RING**

**Propeller Entry**

COMPLETED 100 HOUR PROPELLER INSPECTION USING CESSNA 182 MM 100 HOUR CHECKLIST AS A GUIDE.



RAYMOND KITAGAWA A&P 3159993

Trade Winds Aviation 2505 Cunningham Av San Jose CA 95148


N262CL Propeller 12/24/2008

Tach / TTPROP: 1560.4

1. Dressed small nicks and painted aft face black.

Adjusted propeller governor 1/2 turn in.

I Certify this propeller has been inspected in accordance with an Annual Inspection, was found to be airworthy at this time and is approved for return to service.-----



Ricardo Martinez, A&P / IA 550730870

--	--	--	--	--	--


*West Valley*  
**Flying Club**

1901 Embarcadero Rd. Ste. 100, Palo Alto, Ca 94303 (650)856-2030

DATE:	10/27/2008
REG #:	N262CL
AFTT:	1512
TACH:	1512

**Propeller Entry:**

COMPLETED 50 HOUR PROPELLER INSPECTION USING THE CESSNA 182 MM CHECKLIST AS A GUIDE.



GENE HALVERSON A/P 3290714

*West Valley*  
**Flying Club**

1901 Embarcadero Rd. Ste. 100, Palo Alto, Ca 94303 (650)856-2030

DATE:	3/24/2009
REG #:	N262CL
AFTT:	1609
TACH:	1609

**Propeller Entry:**

COMPLETED 50 HOUR INSPECTION OF THE PROPELLER USING CESSNA 182 MM 50 HOUR CHECKLIST AS A GUIDE.



RAYMOND KITAGAWA A&P 3159993



**West Valley Flying Club**

1901 Embarcadero Rd. Ste. 100, Palo Alto, Ca 94303 (650)856-2030

DATE:	12/30/2009
REG #:	N262CL
AFTT:	1828
TACH:	1828

**Propeller Entry:**

COMPLETED 100 HOUR INSPECTION OF THE PROPELLER USING THE CESSNA 182 MAINTENANCE MANUAL 100 HOUR CHECKLIST AS A GUIDE.

*V. Sharonov*

**VLADIMIR SHARONOV A&P 3287383**

**DIRECTIVE**

**IN SERVICE**

**COMPONENT**


**West Valley Flying Club**

1901 Embarcadero Rd. Ste. 100, Palo Alto, Ca 94303 (650)856-2030

DATE:	01/01/2010
REG #:	N262CL
AFTT:	1828
TACH:	1828

**Propeller Entry:**

Completed Annual Inspection of Propeller. This Propeller is Airworthy.

*Kevin R. Pinger*

**KEVIN R. PINGER A&P 3236526 IA**

**West Valley Flying Club**

1901 Embarcadero Rd. Ste. 100, Palo Alto, Ca 94303 (650)856-2030

DATE:	4/12/2010
REG #:	N262CL
AFTT:	1878
TACH:	1878

**Propeller Entry:**

COMPLETED 50 HOUR INSPECTION OF THE PROPELLER USING THE CESSNA 182 CHECK LIST AS A GUIDE .

*Jasper Sardalla*

**JASPER SARDALLA A&P 3287387**

**West Valley Flying Club**

1901 Embarcadero Rd. Ste. 100, Palo Alto, Ca 94303 (650)856-2030

DATE:	6/16/2010
REG #:	N262CL
AFTT:	1923
TACH:	1923

**Propeller Entry:**

COMPLETED 100 HOUR INSPECTION OF THE PROPELLER USING THE CESSNA 182 MAINTENANCE MANUAL 100 HOUR CHECKLIST AS A GUIDE. DRESSED PROPELLER BLADES.

*David Vital*

**DAVID VITAL A&P 3349651**

12, the work identified in  
in acc... 806 6955.42

2/10/2011  
262CL  
2069  
2069

**West Valley Flying Club**  
1901 Embarcadero Rd. Ste. 100, Palo Alto, Ca 94303 (650)856-2030

DATE:	9/17/2010
REG #:	N262CL
AFTT:	2023
TACH:	2023

**Propeller Entry:**

COMPLETED 100 HOUR INSPECTION OF THE PROPELLER USING THE CESSNA 182 MAINTENACE MANUAL 100 HOUR CHECK LIST AS A GUIDE . DRESSED PROPELLER.

*Jasper Sardalla*  
JASPER SARDALLA A&P 3287387

DIR  
IN SE  
COM

**West Valley Flying Club**  
1901 Embarcadero Rd. Ste. 100, Palo Alto, Ca 94303 (650)856-2030

DATE:	2/10/2011
REG #:	262CL
AFTT:	2069
TACH:	2069

**Propeller Entry:**

COMPLETED ANNUAL INSPECTION OF THE PROPELLER USING THE CESSNA 182 MAINTENANCE MANUAL 100 HOUR CHECKLIST AS A GUIDE. THIS PROPELLER IS AIRWORTHY

*Gene Halverson*  
GENE HALVERSON A&P- I A 3290714

REMARKS

---



---



---



---



---

**West Valley Flying Club**  
1901 Embarcadero Rd. Ste. 100, Palo Alto, Ca 94303 (650)856-2030

DATE:	2/9/2011
REG #:	N262CL
AFTT:	2069
TACH:	2069

**Propeller Entry:**

COMPLETED 100 HOUR INSPECTION OF THE PROPELLER USING THE CESSNA 182 MAINTENACE MANUAL 100 HOUR CHECK LIST AS A GUIDE . DRESSED PROPELLER.

*Jasper Sardalla*  
JASPER SARDALLA A&P 3287387

**West Valley Flying Club**  
1901 Embarcadero Rd. Ste. 100, Palo Alto, Ca 94303 (650)856-2030

DATE:	5/31/2011
REG #:	N262CL
AFTT:	2031
TACH:	2031

**Propeller Entry:**

COMPLETED 50 HOUR INSPECTION OF THE PROPELLER USING THE CESSNA 182 MAINTENANCE MANUAL 50 HOUR CHECKLIST AS A GUIDE. DRESSED PROPELLER.

*Jasper Sardalla*  
JASPER SARDALLA A&P 3287387

REMARKS

---



---



---

West Valley

Flying Club

1901 Embarcadero Rd. Ste. 100, Palo Alto, Ca 94303 (650)856-2030

DATE:	8/13/2011
REG #:	N262CL
TACH:	2182
ACTT:	2182

**Propeller Entry:**

COMPLETED 100 HOUR INSPECTION OF PROPELLER USING THE CESSNA 182 MAINTENACE MANUAL 100 HOUR CHECKLIST AS A GUIDE.



JASPER SARDALLA A&P 3287387

**RECTIVE COMPLIANCE RECORD**

SERVICE COMPONENT	TYPE A.D. (X)		NEXT COMPLIANCE DUE-DATE/ HOURS/OTHER	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER	REMARKS
	ONE-TIME	RE-CURRING			

N262CL  
McCauley B3D36C431  
Serial No. 041928



West Valley Aircraft Services, LLC.  
Embarcadero Rd. Hangar B, Palo Alto, CA 94303  
Tel. (650) 565-0063

5/30/2012  
TACH: 2200.7  
PTSOH: 2200.7

**Propeller Entry:**

I certify that this propeller has been inspected in accordance with an **Annual Inspection** and was determined to be in airworthy condition and is returned to service.



Kevin R. Pinger A&P/LA 3236526





1901 Embarcadero Rd. Ste. 100, Palo Alto, Ca 94303 (650)856-2030

DATE:	7/29/2010
REG #:	N262CL
AFTT:	1979
TACH:	1979

### DIRECTIVE COMPLIANCE RECORD

**Propeller Entry:**

COMPLETED 50 HOUR INSPECTION OF THE PROPELLER USING THE CESSNA 182 MAINTENANCE MANUAL 50 HOUR CHECKLIST AS A GUIDE. DRESSED PROPELLER BLADES.

DAVID VITAL A&P 3349651

N SERVICE COMPONENT	TYPE A.D. (X)		NEXT COMPLIANCE DUE-DATE/ HOURS/OTHER	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER	REMARKS
	ONE-TIME	RE-CURRING			

N262CL  
 McCauley B3D36C431  
 Serial No. 041928



West Valley Aircraft Services, LLC.  
 Embarcadero Rd. Hangar B. Palo Alto, CA 94303  
 Tel. (650) 565-0063

6/14/2013  
 Tach: 2269.1  
 TTP: 2269.1

**Propeller Entry:**

Completed Annual Inspection of the propeller using the Cessna 182 maintenance manual 100 hour checklist as a guide. Removed the spinner, inspected the backing plates, hub, and propeller mounting. Reinstalled the spinner. Dressed the blades. I certify that this propeller has been inspected in accordance with an **Annual Inspection** and was determined to be in airworthy condition and is returned to service.

Kevin R. Pinger A&P LA 3236526

returned to service.



Kevin R. Pinger A&P LA 3236526

N262CL  
McCauley B3D36C431  
Serial No. 041928




West Valley Aircraft Services, Inc.  
Embarcadero Rd. Hangar B, Palo Alto, CA 94303  
Tel. (650) 565-0063

8/22/2014  
Tach: 2535.0  
TTP: 2535.0

**Propeller Entry:**

Completed Annual Inspection of the propeller using the Cessna 182 maintenance manual 100 hour checklist as a guide. Removed the spinner, inspected the backing plates, hub, removed the propeller to replace the flywheel, reinstalled and torqued and safetied IAW with the Cessna 182 maintenance manual. Reinstalled the spinner. Dressed the blades. I certify that this propeller has been inspected in accordance with an **Annual Inspection** and was determined to be in airworthy condition. This propeller is returned to service.



Kevin R. Pinger A&P LA 3236526