

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL 3C1-R919A1

PROPELLER S/N SR7

LOGBOOK # 1

PROPELLER MAINTENANCE RECORD

Position One

Propeller Model 3C1-R919A1

Propeller S/N SR7

Blade Design 76C03-2

Blade S/N's

No. 1 B8617

No. 2 B8605

No. 3 B5633

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/Feather _____

Start Lock _____

Low _____

Reverse _____

Aircraft Manufacturer Cirrus Design Corp.

Aircraft Model SR20

S/N 2467

Registration N878GR

Date	Propeller TSN	TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
------	------------------	-----	------------	---

Hawk Aviation LLC

N878GR – Propeller Logbook Entry

MAKE: Cirrus Aircraft

DATE: 3/6/19

MODEL: SR20


HOBBS: 32.8

S/N: 2467

FLIGHT: 22.9

Work accomplished:

Removed and installed propeller P/N 3C1-R919A1 S/N 7 IAW CDC AMM Chapter 61-10

Trevor Hawk 

A&P/IA 3341763 – Cirrus Aircraft Trained Technician

Southeast Aero Services Inc.

St Augustine, FL.

Phone (904) 824-1899/Fax (904) 824-6334

Hartzell 3C1-R919A/76C03-2

s/n:SR7

N858GR

12-10-19 Hobbs:74.1hrs. Flight Hr:55.0hrs. Prop Total Time:55.0hrs. Completed an Annual inspection in accordance with 14CFR 43 Appendix D with references to Chapters 4&5 Cirrus SR20 maintenance manual this date. AD's checked thru FAA Bi-Weekly 2019-24. No AD's due at this time. Serviced hub with Aeroshell #6 lubricant.

I certify this Propeller has been inspected in accordance with an Annual inspection and was determined to be in an Airworthy condition at this time.


Bryan M Wood A&P3216290IA

Southeast Aero Services Inc.

St Augustine, FL.

Phone (904) 824-1899/Fax (904) 824-6334

Hartzell 3C1-R919A/76C03-2

s/n:SR7

N878GR

01-05-21 Hobbs:105.2hrs. Flight Hr:76.9hrs. Airframe Total Time:76.9hrs. Completed an Annual inspection in accordance with 14CFR 43 Appendix D with references to Chapters 4&5 Cirrus SR20 maintenance manual this date. AD's checked thru FAA Bi-Weekly 2020-26. No AD's due at this time. Serviced hub with Aeroshell #6 lubricant.

I certify this Propeller has been inspected in accordance with an Annual inspection and was determined to be in an Airworthy condition at this time.


Esad Mujic A&P3034119IA

Date Propeller TSN TSO A/C Hrs

Description of all operations pertaining to Airworthiness Directives,
Service Documents, Overhaul, Major or Minor Repair, and Inspections.

Southeast Aero Services Inc.

St Augustine, FL.

Phone (904) 824-1899/Fax (904) 824-6334

Hartzell 3C1-R919A/76C03-2

S/N: SR7

N878GR

21 January 2022

Hobbs: 146.3 hrs.

Propeller Total Time: 108.5 hrs.

Flight Hr: 108.5 hrs.

Completed an Annual inspection in accordance with 14CFR 43 Appendix D with references to Chapters 4&5 Cirrus SR20 maintenance manual this date. AD's checked thru FAA. Bi-Weekly 2022-2. No AD's due at this time. Serviced hub with Aeroshell #6 lubricant.

I certify this Propeller has been inspected in accordance with an Annual inspection and was determined to be in an Airworthy condition at this time.

William T. Rhodes A&P3078721IA

Southeast Aero Services Inc.

St Augustine, FL.

Phone (904) 824-1899/Fax (904) 824-6334

Hartzell 3C1-R919A/76C03-2

S/N: SR7

N878GR


8 February 2023

Hobbs: 185.4 hrs.

Propeller Total Time: 136.4 hrs.

Flight Hr: 136.4 hrs.

Completed an annual inspection in accordance with 14CFR 43 Appendix D with references to Chapters 4&5 Cirrus SR20 maintenance manual this date. AD's checked thru FAA. Bi-Weekly 2023-03. No ADs due at this time. Serviced hub with Aeroshell #6 lubricant. I certify this Propeller has been inspected in accordance with an annual inspection and was determined to be in an Airworthy condition at this time.



Christopher J Nameth A&P38059011A