

**HARTZELL**

# PROPELLER LOGBOOK

PROPELLER MODEL PHC-J3YF/F7694

PROPELLER S/N FP2595B

LOGBOOK # 1

# PROPELLER MAINTENANCE RECORD

Position Front

Propeller Model DHC-J34F-1RF/F7694

Propeller S/N FP2595B

Blade Design \_\_\_\_\_

Blade S/N's

No. 1 J89869

No. 2 J89868

No. 3 J89867

No. 4 \_\_\_\_\_

No. 5 \_\_\_\_\_

No. 6 \_\_\_\_\_

Spinner Assembly Part No. \_\_\_\_\_

PITCH RANGE

High/Feather \_\_\_\_\_

Start Lock \_\_\_\_\_

Low 14.1

Reverse \_\_\_\_\_

Aircraft Manufacturer Cirrus

Aircraft Model SR22

S/N 755

Registration N102KW



PROP MODEL:  
PROP S/N:  
REG. NO: N102KW  
WORK ORDER:  
1300-12-2005



### Twin Cities Aviation, Inc.

8891 Airport Rd #A-2  
Blaine, Minnesota 55449  
Phone: 763-784-9165

DATE: 12/16/2005  
A/C TSN: 813.2  
PROP TT:  
HOBBS: 813.2

### Prop Entries

Lubricated prop with aeroshell 6. C/W an annual Prop inspection IAW Cirrus SR 22 MM and IG. AD's researched to date. See AD listing for pertinent details. All Cirrus SB's researched to date. Ground run, ops and leak check sat. I certify that I have inspected this prop iaw an annual inspection and it was determined to be airworthy with respect to work performed at this date and time. The following discrepancies were addressed:---Dressed prop blades and painted blade faces and tips.

The aircraft, airframe, engine, propeller, or appliance above was repaired and / or inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service.

DATE: 12/16/2005

SIGNED:

Jeff Iskierka, IA: 470046442

Work Order: 1300-12-2005

Printed by EBis 3 (datcomedia.com)

### Propeller Log

### Jetsun Aviation Centre Sioux Gateway Airport

DATE	REGISTRATION	MAKE/MODEL	S/N	HOBBS	ACTT
12/1/2006	N102KW	CIRRUS SR22	755	925	925

*Hartzell Model PHC-J3YF/F7694 S/N: FP2595B TSN: 925*

*Complied with a 100hr inspection in accordance with FAR 43 Appendix "D" by using Cirrus MM 05-20-00 as a guide. Lubricated and dressed leading edges as required.*

**I certify that this propeller has been inspected in accordance with an 100 inspection and was determined to be in Airworthy condition.**

**Details pertinent to this inspection are on file under W.O. # 13836 dated: December 01, 2006.**

Signed: , Inspector for JetSun Aviation Centre, CRS# SG7R549J



**AirQuest Aviation**

485 Airport Road  
Butler, PA 16002



Date: 6/19/2009; Aircraft: N102KW; Type: CIRRUS SR22; S/N: 0755

Complied with annual inspection of the aircraft propeller in accordance with Cirrus maintenance manual. The Aircraft and/or Component Identified above was Inspected and/or Repaired in accordance with current FAA Regulations and is Approved for Return to Service. Pertinent Details of the Inspection / or Repair are on File at this Repair Station. I certify that this propeller has been inspected in accordance with a annual inspection and was determined to be in airworthy condition.

Hobbs time: 1095.9 WO#: 09-0793

Signed Lathan Ersk Date 6/19/09

AirQuest Aviation 485 Airport Rd. Butler, PA 16002

Q3ER924K


# TOM'S AIRCRAFT SERVICE, INC.

1559 AIRPORT ROAD  
(FKL) FRANKLIN, PA 16323  
814-437-3000

---


Reg. # N102KW	Model: Cirrus SR22
Serial # 0755	Date: 04/16/10
ETT: 1117.5	Hobb: 1117.5

---

Completed 100hr. annual inspection in accordance with Hartzell propeller owner's manual. Dressed prop. Lubed with Aeroshell #6.  
AD's through Triton Aviation Data Corp.

I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

JOHN PINK



A&P2710781IA

**TOM'S AIRCRAFT SERVICE, INC.**

1559 AIRPORT ROAD  
(FKL) FRANKLIN, PA 16323  
814-437-3000

Reg. # N102KW

Model: Cirrus SR22

Serial # 0755

Date: 03/16/11

ETT: 1170.6

Hobb: 1170.6

Completed 100hr. annual inspection in accordance with Hartzell Propeller owner's manual. Dressed prop. Lubed with Aeroshell #6 grease. AD's through Triton Aviation Data Corp.

I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

JOHN PINK



A&P2710781IA





**TOM'S AIRCRAFT SERVICE, INC.**

1559 AIRPORT ROAD  
(FKL) FRANKLIN, PA 16323  
814-437-3000

Reg. # N102KW

Model: Cirrus SR22

Serial # 0755

Date: 04/10/2013


TT: 1229.3

Hobb: 1229.3

Triton Aviation Data Corp.

I certify that this propeller has been inspected in reference with an annual inspection and was determined to be in airworthy condition.

JOHN PINK



A&P2710781IA

Date	Propeller TSN    TSO		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
------	-------------------------	--	------------	---

**TOM'S AIRCRAFT SERVICE, INC.**

1559 AIRPORT ROAD  
(FKL) FRANKLIN, PA 16323  
**814-437-3000**

Reg. #	N102KW	Model:	Cirrus SR22
Serial #	0755	Date:	04/15/2014
TT:	1269.8	Hobb:	1269.8

Triton Aviation Data Corp.

I certify that this propeller has been inspected in reference with an annual inspection and was determined to be in airworthy condition.

JOHN PINK  A&P2710781IA

**TOM'S AIRCRAFT SERVICE, INC.**

**1559 AIRPORT ROAD  
(FKL) FRANKLIN, PA 16323  
814-437-3000**

Reg. # N102KW

Serial # 0755

TT: 1299.9

Model: Cirrus SR22


Date: 03/03/2015

Hobbs : 1299.9



Triton Aviation Data Corp.

I certify that this propeller has been inspected in reference with an annual inspection and was determined to be in airworthy condition.

JOHN PINK



A&P2710781IA

Date	Propeller		A/C	Description of all operations pertaining to Airworthiness Directives,
	TSN	TSO		
				<p><b>N 102KW HOBBS:1330.5 4/8/2016 MOD:PHC-J3YF/F7694 SN:FP2595B</b></p> <p>C/W annual inspection, Ground run aircraft, operational check OK at this time. I certify that this prop has been inspected in accordance with FAR43 AppD an annual inspection and is determined to be in airworthy condition at this time.</p> <p><i>[Signature]</i> App 197660316JA</p> <p>All Points Aviation ~ Meadville Airport~ KGKJ ~(814) 724-6114</p> 
				<p><b>N 102KW HOBBS:1366.5 6/6/2017 MOD:PHC-J3YF/F7694 SN:FP2595B</b></p> <p>C/W annual inspection, Ground run aircraft, operational check OK at this time. I certify that this prop has been inspected in reference to FAR43 AppD , annual inspection and is determined to be in airworthy condition at this time.</p> <p><i>[Signature]</i> App 197660316JA</p> <p>All Points Aviation ~ Meadville Airport~ KGKJ ~(814) 724-6114</p> 





**N102KW** HOBBS:1530.3 7/26/2022 MOD:PHC-J3YF/F7694 SN:FP2595B

C/W annual inspection, Ground run aircraft, operational check OK at this time. I certify that this prop has been inspected in reference to FAR43 AppD. annual inspection and is determined to be in airworthy condition at this time.

*[Handwritten Signature]*  
App 1976623/6TA

All Points Aviation ~ Meadville Airport~ KGKJ ~(814) 724-6114



**N102KW** HOBBS:1542.9 11/24/2023 MOD:PHC-J3YF/F7694 SN:FP2595B

C/W annual inspection, Ground run aircraft, operational check OK at this time. I certify that this prop has been inspected in reference to FAR43 AppD. annual inspection and is determined to be in airworthy condition at this time.

*[Handwritten Signature]*  
App 1976623/6TA

