

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL _____

PROPELLER S/N _____

N297CD

LOGBOOK # _____

PROPELLER MAINTENANCE RECORD

Position Front

Propeller Model BHC-J2YF-1BF

Propeller S/N EF295B

Blade Design F7694

Blade S/N's

No. 1 J75656 (R)

No. 2 J75655 (R)

No. 3 _____

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/Feather _____

Start Lock _____

Low _____

Reverse _____

Aircraft Manufacturer _____

Aircraft Model _____

S/N _____

Registration _____

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		

SILVERHAWK AVIATION INC. Lincoln, NE

Date: 11-02-2004 W.O. 04-9287 N297CD Tach: 234.1

ACTT : 234.1 ETT: 234.1 ETSOH: 234.1 PTT: 234.1 PSTOH: 234.1

Completed Annual inspection IAW Cirrus Design Inspection checklist on propeller.

END

Tach/Hr Meter 234-1 Total Time 234-1

I certify this (aircraft) (engine) (propeller) has been inspected in accordance with a/an ANNUAL inspection as per FAR 91.409 A and was determined to be in an airworthy condition.

Dated 11-2-04 W.O. 04-9287 Signed [Signature]

Silverhawk Aviation CRS # YQSR759U
Lincoln, NE 68524

SO#	06-10787	SILVERHAWK JET CENTER			DATE	03/08/06
REG.	N297CD	Lincoln Municipal Airport [LNK]			ACTT	334.8
MAKE	Hartzell	MODEL	BHC-J2YF-1BF	PTT	334.8	HOUR
		SERIAL NO.	EF295B	PTSOH	334.8	

1. Compled with an Annual inspection IAW Cirrus Design SR20 Maintenance Manual checklist.
2. Dressed blades as needed.

I certify this (aircraft) (engine) (propeller) has been inspected in accordance with a/an Annual inspection as per FAR 91.409 (a) (1) and was determined to be in an airworthy condition.

Dated 03/08/06 W.O. 06-10787 Signed [Signature]

Silverhawk Jet Center CRS # YQSR759U
Lincoln, NE 68524

7-17-2007

Prop. TT: 397.1

Hobbs: 397.1

N297CD Prop. Log

Completed an Annual inspection in accordance with Cirrus Design AMM Chapter 5-20 Scheduled Maintenance Checks. Lubricated the propeller using Aeroshell 6.

I certify that this propeller has been inspected in accordance with an Annual Inspection and has been determined to be in airworthy condition. See W.O . 19826 for details.



Anthony D. Stanton
Executive Beechcraft Inc.
280 Gardner Drive
New Century, Kansas 66031
CRS YEBR071L

2

STRATUS AVIATION MAINTENANCE


Midwest National Air Center 13106 Rhodus Road Excelsior Springs MO 64024

This constitutes an official maintenance record per FAR 43.9 & 43.11.

PROPELLER S/N: EF295B

Reg. No.	Date	Tach	PROP TT
N297CD	11/1/2008	442	442

I certify that this **PROPELLER** has been inspected in accordance with an **"ANNUAL"** inspection and was determined to be in airworthy condition. File name:2008 - 10 - 235

Inspector Signature  **A&P 3201708 IA**
Richard E. Anderson

Date	Propeller TSN TSO		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
3-19-2010			472.0	Insp for Annual insp - OK for service
				Lubricated prop
				Charles J West FA ATP 1714637
			605.7 hrs	
8-20-2013				Insp for annual insp - OK for service
				Charles J West IA ATP 1714637
12-1-2015			750.8 hrs	
				Insp for Annual insp. OK for service
				Charles J West IA ATP 1714637

2/1	823.3	100hr	ANNUAL INSPECTION	Completed.

INSPECTED
 IN ACCORDANCE WITH 100hr/ANNUAL INSPECTION
 AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION
 THIS DATE.
 W/O # WA1605831 DATE 2-1-2018 HRS 823.3
 SIGNATURE [Signature]
 AUTOPROPS CENTRAL, INC

PROP MODEL:
 BHC-J2YF-1BF
 PROP S/N: EF295B
 REG. NO: N297CD
 WORK ORDER: 0291

 **Mistwood Aviation Services, LLC.**
 2404 Northline Ind. Blvd.
 Maryland Hts., MO 63043
 Phone: 314-991-6000

DATE: 27 March, 2018
 A/C TSN: 992.7
 PROP TT: 992.7
 TACH: 992.7

Prop Entries

Performed Hartzell Propeller 100 Hour/Annual Inspection IAW Cirrus SR20 Aircraft Maintenance Manual 12137-001 Reissue B June 2010, Rev B8 19
 Sep 2017 and Hartzell Propeller Owners Manual 115N.

I certify this propeller has been inspected in accordance with a 100 Hour / Annual Inspection meeting the intent of 14 CFR 91.409 and Part 43 Appendix D
 and has been determined to be in an airworthy condition and is approved for return to service. Pertinent details of the inspection/repairs are on file at
 Mistwood Aviation Services under the above noted work order.

DATE: 27 March, 2018 SIGNED [Signature] Work Order: 0291
 John Merriman, IA: 2787167 Printed by EBis 3 (datcomedia.com)

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
				ARAPAHOE AERO 12760 EAST CONTROL TOWER ROAD ENGLEWOOD, COLORADO 80112 (303) 799-8386 N297CD Hartzell BHC-J2YF-1BF/F7694 S/N: EF295B Total Time: 1166.0 13 April 2019 Hobbs Meter: 1166.0 Calendar Time: 16 Years 8 Months 100 Hour Inspection for Annual completed this date using the Cirrus SR20 Inspection Form as a guide. Inspected propeller hub and blades. Dressed leading edges of blades and painted blade faces. AD's checked through Biweekly 2019-07. I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HOUR INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. <i>L. John Wells</i> L. John Wells A&P 3221132 w/o 39983
				ARAPAHOE AERO 12760 EAST CONTROL TOWER ROAD ENGLEWOOD, COLORADO 80112 (303) 799-8386 N297CD Hartzell BHC-J2YF-1BF/F7694 S/N: EF295B Total Time: 1306.5 21 May 2020 Hobbs Meter: 1306.5 Calendar Time: 17 Years 9 Months 100 Hour Inspection for Annual completed this date using the Cirrus SR20 Inspection Form as a guide. Inspected propeller hub and blades. Dressed leading edges of blades and painted blade faces. AD's checked through Biweekly 2020-10. I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HOUR INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. <i>Randy C. Johnson</i> Randy C. Johnson A&P 3123186 w/o 41194

A/C Make: Cirrus
 A/C Model: SR-20
 Reg. No.: N297CD
 S/N: 1232
 Tach: 1393.3
 A/F TT: 1393.3

EL AERO SERVICES, LLC.

815 Murray Way
 Elko, NV 89801

F.A.A. Certificated Repair Station #9WQR791C

PROPELLER LOGBOOK INSERT

Propeller Make: HARTZELL
 Propeller Model: BHC-J2YF-1BF/F7694
 S/N: EF295B
 Prop TT: 1393.3
 S.M.O.H.: 1393.3
 W.O. #: EKO-20-23440

The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details are on file at this agency.

1) - Performed 100 hour and a Annual inspection using Cirrus SR-20 Inspection Form, HARTZELL Propeller Manual 115N inspection and check 61-00-15 Rev. 6 dated Sep/00, and El Aero Services Form E-04. Next 100 hour due at 1493.3 TT. Next Annual due on or before 11/30/21. 2) – **I certify that this Propeller has been inspected in accordance with an Annual and a 100-hour inspection and was determined to be in an airworthy condition.** Signed *[Signature]* Inspector for El Aero Services, LLC. 9WQR791C.

11/20/2020

For repair station of El Aero Services, LLC.

Form EA-13

Stew's Aero Services 1999 Arrowhead Dr Carson City, NV 89706 12/10/2021
 N297CD Model: BHC-J2YF-1BF S/N: EF295B Hobbs: 1457.3 TSP0H: 22.3

Performed 100-hour/Annual inspection IAW McCauley and Cirrus maintenance manuals. Adjusted prop governor control cable to prevent over speeding. All applicable AD's complied with at this time, see separate AD list. I certify that this propeller has been inspected IAW a 100-hour/Annual inspection and has been found airworthy at this time.

[Handwritten Signature]

1861869 A&P/IA

perations pertaining to Airworthiness Directives,
 Overhaul, Major or Minor Repair, and Inspections.

Registration N297CD
 Make Cirrus
 Model SR20
 Serial # 1232



Sierra Mountain Aviation, Inc.
 13308 Nevada City Ave, Grass Valley, CA 95945
Prop

Date 12/21/2022
 Prop T/T 1601.8
 SMOH 166.8
 Hobbs 1601.8
 Work Order 23269

Complied with an Annual Inspection service per SMA Checklist
 Dressed and painted face of prop.

I certify that this propeller has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition at this time and aircraft is returned for service

Signature: *[Handwritten Signature]*

Daniel L. Grass A&P IA 3577254
 Sierra Mountain Aviation, Inc. 530.273.5273

