


N454SR



mt-propeller

The Winner's Propeller

PROPELLER LOGBOOK

EASA DE.21G.0008 / EASA.21J.020

Owner Name _____

Address _____

Propeller Model MTV-14-D

Blade Model 193-306

Hub Serial No. 211501

Blade Serial No. 1 AMH-88703

2 AMH-88704

3 AMH-88705

4 AMH-88706

5 _____

6 _____

Propeller Diameter: 193 cm ± 0,5 cm

Low Pitch: 9,5 ° ± 0,2 ° TCI: 72 Month


High Pitch: 38 ° ± 1 ° TBO: 2400 Hrs.

Feathering: / ° ± / °

Reverse: / ° ± / °

at radius station: 72,5 cm

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
Nov 05 2021	00:00	/	Manufactured	
NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12				



Date: 3/10/22 Total Time: 0.0

Reassembled propeller in accordance with MT-Propeller Overhaul Manual E-220.

Signature: *Jim Paine* A&P 2756905

Registration N454SR
Make Cirrus
Model SR22
Serial # 2428



Sierra Mountain Aviation, Inc.
13308 Nevada City Ave, Grass Valley, CA 95945
Prop

Date 05/27/2022
Prop T/T 0.0
SMOH N/A
FLT 1615.1
Work Order 23152

Installed new MT propeller per STC SA02924CH
Filed 337 with FAA, updated W&B and equipment list

I certify that this propeller has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition at this time and aircraft is returned for service

Signature: _____

Daniel L. Grass A&P IA 3577254
Sierra Mountain Aviation, Inc. 530.273.5273

Registration N454SR
Make Cirrus
Model SR22
Serial # 2428



Sierra Mountain Aviation, Inc.
13308 Nevada City Ave, Grass Valley, CA 95945
Prop

Date 06/01/2023
Prop T/T 80.4
SMOH N/A
Flt time 1695.5
Work Order 23338

Complied with an Annual Inspection service per SMA Checklist
Dressed and painted face of prop.
AD #2022-18-12-02 Propeller Blade Lag Screws with Reduced Fatigue Strength
N/A by prop S/N

I certify that this propeller has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition at this time and aircraft is returned for service

Signature: _____

Daniel L. Grass A&P IA 3577254
Sierra Mountain Aviation, Inc. 530.273.5273



Steel Aviation · 53 North Street Ext · Phillipsburg, Ohio 45354 · 937 332 7587

N454SR

HOBBS: 1837.9

MT Propeller, S/N: 211501

TACH: 1746.3

PTSN: 131.2

June 25, 2024

C/W Annual Inspection in accordance with FAR 43 Appendix D - using the MT Propeller E-124 as a guide.

I certify that this Propeller has been inspected in accordance with an (annual) inspection and was determined to be in airworthy condition. Details of work performed are on file with Steel Aviation under work order: WO_458.

Jeff Pleiman A/P I/A 3304319

A handwritten signature in black ink, appearing to read "Jeff Pleiman", is written over a horizontal line.