




*The Standard*

# **PROPELLER LOG**

**ASA-SP-L**

BOOK # 1



*The Standard*

# **PROPELLER LOG**

**ASA-SP-L**

## Propeller Record General Information

Propeller Manufacturer Hartzell

Model HC-13Y1R-1N

Hub Series # NY230B

Date of Manufacture \_\_\_\_\_

Type \_\_\_\_\_

Blade # A9646

A9655

A9607

Make/Model

Serial #

Aircraft Installed On: \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS



SPECIAL SERVICES CORPORATION

Date: 04/07/2019

Hobbs: 447.7

Propeller: Hartzell

Prop. model: HC-I3Y1R-1N

Prop. TSOH: N/A

N200JP

Fit: N/A

Prop. S/N: NY230B

Prop. TSN: 447.7

Performed an annual/100 hour inspection in scope and detail of items according to FAR Part 43 Appendix D. All applicable airworthiness directives through 04/07/2019 have been reviewed and complied with. Performed a ground run and leak check.

Work was also performed by Charles Baize, David Tidwell, and Christopher Nelson.

I certify that this propeller has been inspected in accordance with an Annual/100 hour Inspection and found to be in airworthy condition on this date.

Ronald Allen Campbell IA 001959044 *Ronald Allen Campbell*

Next Inspection  
Due:

Time Since  
Overhaul

Mech. Cert. # or Repair Station #

# HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS ☐



**MartinAviation®**

N200JP  
HARTZELL

PIPER PA-46-350P  
HC-13Y1R-1N

S/N 4636649  
S/N NY230B

ACTT: 748.3  
PROP TT: 748.3

Performed the Following Maintenance Actions:

1. Removed Hartzell Propeller HC-13Y1R-1N, S/N NY230B for overhaul by American Propeller Service

Signed

*Michael Rogers*

W.O.# 23569

Dated 05/04/2021

Michael Rogers – Inspector  
MARTIN AVIATION, MAINTENANCE  
19300 IKE JONES ROAD, SANTA ANA, CA 92707  
CRS M8VR406N

Page 1 of 1

Mech. Cert. # or Repair Station # \_\_\_\_\_

**Total Time  
in Service**

**Description**

**Time Since  
Overhaul**

Mech. Cert. # or Repair Station # \_\_\_\_\_

#

# HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS ☐



**MartinAviation®**

Year:

Date:

Next In Due:

N200JP  
HARTZELL

PIPER PA-46-350P  
HC-I3Y1R-1N

S/N 4636649  
S/N NY230B

HOBBS: 748.3  
PROP TT: 748.3

ACTT: 748.3  
TSPOH: 0.0

Performed an **Annual/100 HR Inspection** in accordance with 14 CFR Part 43 using the Piper PA-46-350P Airplane Maintenance Manual P/N 761-876, Rev. PR210315 dated May 3, 2021, Ch. 5-20-00, 5. Scheduled Maintenance Checklist & 5-30-00 Special Inspections; the Lycoming TIO-540-AE2A Series Operator's Manual P/N 60297-27, Rev. 60297-27-3 dated 11/06, Section 5; and the Hartzell Propeller Owner's Manual No. 145, Ch. 61-00-45, Rev. 20 dated Apr/21, Page 5-10, Section 3.A. Periodic Inspections as a guide.

Accomplished the requirements of PA-46-350P AMM sections 04-00-00, 05-20-00 and 05-30-00 as follows:

Year:

Date:

Next In Due:

100hr/12mo Propeller Lubrication

Performed the following maintenance actions:

1. Reinstalled Hartzell P/N HC-I3Y1R-1N, S/N NY230B Propeller following overhaul by Ameritech Industries dba American Propeller Service, Cert. No. NO3R717L, W.O. 25868-05-2021 dated 24 May 2021 IAW Piper AMM, Ch. 61-10-00. Operational check good.

ADs checked for compliance through BW ~~2021-09~~ <sup>2021-11 MSA</sup> and AD listing updated.

I certify that this propeller has been inspected in accordance with an Annual/100 HR Inspection and was determined to be in airworthy condition with respect to the work performed above.

Year:

Date:

Next In Due:

Signed

W.O# 23569

Dated 05/28/2021

Michael Rogers – Inspector  
Martin Aviation, Maintenance  
19300 Ike Jones Road, Santa Ana, CA 92707  
CRS #M8VR406N

# ☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

PROP MODEL:  
HC-I3Y1R-1N  
PROP S/N: NY230B  
REG. NO: N200JP  
WORK ORDER:  
5971-05-2022



## G. H. Enterprises, Inc.

9210 CE Woolman Dr.  
Baton Rouge, LA 70807  
Phone: 225-356-4008

DATE: 20 July, 2022  
A/C TSN: 931.2  
PROP TT: 931.2  
TSPOH:  
HOBBS: 931.2

### Prop Entries

(3) Complied with propeller annual inspection IAW Piper MM 05-20-00.

THE AIRCRAFT AND / OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED IN ACCORDANCE WITH THE INSTRUCTIONS AND PROCEDURES FOR AN INSPECTION PROGRAM REQUIRED BY FAR 91-409 (d) AND HAS BEEN FOUND TO BE IN AN AIRWORTHY CONDITION AND IS APPROVED FOR RETURN TO SERVICE.  
COMPLIED WITH ANNUAL INSPECTION

DATE: 20 July, 2022

SIGNED:

A handwritten signature in blue ink, appearing to read 'Gerald Huggins', is written over a horizontal line.

Gerald Huggins, IA: 2003581

Work Order: 5971-05-2022

Printed by EBis 3 (datcomedia.com)

Year: \_\_\_\_\_ In Service

Date:

Next Inspection  
Due:

Time Since  
Overhaul

Mech. Cert. # or Repair Station # \_\_\_\_\_

# HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS ☐

Year

Date

Next  
Due:

Hartzell HC-13Y1R-1N SN NY230B PROP TT.1057.5 TSPOH 309.2  
CW propeller inspection per Piper Mirage maintenance manual inspection  
guide. I certify that this propeller has been inspected IAW a 100 hr/annual  
inspection and was determined to be in an airworthy condition.

*Gaylord A. Syrstad*

Gaylord A. Syrstad A&P 3024178 IA G's Aviation Service LLC

Year

Date

Next Inspection  
Due:

Time Since  
Overhaul

Mech. Cert. # or Repair Station #

Year: \_\_\_\_\_

Total Time  
in Service

Description

Date:

CONTINUE ON BOOK #2

Next Inspection  
Due:

Time Since  
Overhaul

Mech. Cert. # or Repair Station #

LOC: 21JD P/N: 13-32370  
ASA PROPELLER LOG, SFTCVR 20 PGS



153570666 PO: 425069 LOT: 30-18714