



SUPPLEMENTAL MAINTENANCE LOGBOOK-SECTION:

Page:

wo: MO_1878	AeroMeph	Propeller - page 1 of 1
Aeromech Aircraft Maintenance - 6799 N Glen Harbor Blvd - Glendale, AZ 85307 - 6238779334		
N9629J TACH: 4762.26	Sensenich, S/N: 25570K PTSO: 2192.46	November 01, 2024
Dressed propeller using AC43-13-1b as a guide.		
This propeller has been inspected in accordance with a 100 HOUR INSPECTION and was found Airworthy and approved for return to service at this time. AD's checked thru 2024-21. Details of work performed are on file with Aeromech Aircraft Maintenance under work order: MO_1878.		
Mark Swartwood A&P3567883IA 		

wo: MO_2361	AeroMeph	Propeller - page 1 of 1
Aeromech Aircraft Maintenance - 6799 N Glen Harbor Blvd - Glendale, AZ 85307 - 6238779334		
N9629J TACH: 5052.17	Sensenich, S/N: 25570K PTSO: 2482.37	November 14, 2025
Dressed propeller using AC43.13-1b chapter 8 as a guide.		
This propeller has been inspected in accordance with a 100 HOUR INSPECTION and was found Airworthy and approved for return to service at this time. AD's checked thru 2025-22. Details of work performed are on file with Aeromech Aircraft Maintenance under work order: MO_2361.		
Mark Swartwood A&P3567883IA 		

NOTE: THIS DOCUMENT IS PART OF THE PERMANENT MAINTENANCE RECORDS.
DO NOT DESTROY