

N284DP



PROPELLER LOGBOOK

PROPELLER MODEL 3C1-R919A1

PROPELLER S/N SR99

LOGBOOK # _____

662-09-2024 (10-15-2024)

MAKE: Cirrus
MODEL: SR20
S/N: 8760
REG. NO: N284DP
PROP MAKE: HARTZELL
PROP MODEL: 3C1-
R919A1
PROP SN: SR99

Midwest Corporate Air
3100 State Route 47 West
Bellefontaine, OH 43311

W/O #: 662-09-2024
DATE: 10-15-2024
A/C Tach: 1052.2
Prop TT: 0.1

Propeller Entries

• Performed 100 hour inspection IAW MM and inspection checklist.... • Installed new Hartzell Propeller P/N 3C1-R919A1/76C03-2, S/N SR99. See C of C dated 9/25/2024.... • Researched and complied with all Airworthiness Directives. See compliance records.

I certify that this aircraft has been repaired and inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition at this time.

DATE: 10-15-2024

SIGNED:

Alvin Minzler
Alvin Minzler
FAA Cert 3099793 A&P

WORK ORDER: 662-09-2024

Printed by EBIS (EBISCloud.com)

818-01-2025 (01-13-2025)

MAKE: Cirrus
MODEL: SR20
S/N: 8760
REG. NO: N284DP
PROP MAKE: HARTZELL
PROP MODEL: 3C1-
R919A1
PROP SN: SR99

Midwest Corporate Air
3100 State Route 47 West
Bellefontaine, OH 43311

W/O #: 818-01-2025
DATE: 01-13-2025
A/C Tach: 1151.6
Prop TT: 99.5

Propeller Entries

• Performed 100 hour inspection IAW MM and inspection checklist.... • Researched and complied with all Airworthiness Directives. See compliance records.

I certify that this aircraft has been repaired and inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition at this time.

DATE: 01-13-2025

SIGNED:

Alvin Minzler
Alvin Minzler
FAA Cert 3099793 A&P

WORK ORDER: 818-01-2025

Printed by EBIS (EBISCloud.com)

MAKE: Cirrus
MODEL: SR20
S/N: 8760
REG. NO: N284DP
PROP MAKE: HARTZELL
PROP MODEL: 3C1-
R919A1
PROP SN: SR99

Midwest Corporate Air
3100 State Route 47 West
Bellefontaine, OH 43311

W/O #: 977-04-2025
DATE: 04-16-2025
A/C Tach: 1252.0
Prop TT: 199.9

Propeller Entries

• Performed 100 hour inspection IAW MM and inspection checklist... • Researched and complied with all Airworthiness Directives. See compliance records.

I certify that this aircraft has been repaired and inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition at this time.

DATE: 04-16-2025

SIGNED: 

Tim Kerns
FAA Cert A&P 3390695 IA

WORK ORDER: 977-04-2025

Printed by EBIS (EBISCloud.com)

1068-06-2025 (06-05-2025)

Page 1 / 1

MAKE: Cirrus
MODEL: SR20
S/N: 8760
REG. NO: N284DP
PROP MAKE: HARTZELL
PROP MODEL: 3C1-
R919A1
PROP SN: SR99

Midwest Corporate Air
3100 State Route 47 West
Bellefontaine, OH 43311

W/O #: 1068-06-2025
DATE: 06-05-2025
A/C Tach: 1351.4
Prop TT: 299.3

Propeller Entries

• Performed 100 hour inspection IAW Cirrus MM and inspection checklist... • Researched and complied with all Airworthiness Directives. See compliance records.

I certify that this aircraft has been repaired and inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition at this time.

DATE: 06-05-2025

SIGNED: 

Tim Kerns
FAA Cert A&P 3390695 IA

WORK ORDER: 1068-06-2025

Printed by EBIS (EBISCloud.com)

1197-07-2025 (07-29-2025)

W/O #: 1197-07-2025
DATE: 07-29-2025
A/C Tach: 1448.7
Prop TT: 396.6

MAKE: Cirrus
MODEL: SR20
S/N: 8760
REG. NO: N284DP
PROP MAKE: HARTZELL
PROP MODEL: 3C1-
R919A1
PROP SN: SR99

Midwest Corporate Air
3100 State Route 47 West
Bellefontaine, OH 43311


Propeller Entries

- Performed ANNUAL inspection IAW MM and inspection checklist....
- Researched and complied with all Airworthiness Directives. See compliance records.

I certify that this aircraft has been repaired and inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition at this time.

DATE: 07-29-2025

SIGNED:


Tim Kerns
FAA Cert A&P 3390695 IA

WORK ORDER: 1197-07-2025

Printed by EBIS (EBISCloud.com)