


E3081

41



**McCAULEY**  
**PROPELLER LOGBOOK**

# INSTALLATION HISTORY

Date	Aircraft Model & Registration No.	Engine Serial Number & Position
	THIS PROPELLER WAS MANUFACTURED	
DEC 18 1996	NEW AT McCUALEY ACCESSORY DIVISION, INSPECTED AND FOUND TO BE AIRWORTHY ON THIS DATE.	M 356
3-3-97	A36	N1113H
		682608

Reg: N1113H

Date: 9/3/97

WorkOrder: 13992

Mod: A36

HourMeter: 101.0

S N: E-3081

Raytheon Aircraft Services, Inc.

TotalTime: 101.0

1. Complied with an Annual Inspection using Beech form p/n: 98-32227H.

**I CERTIFY THAT THIS Propeller HAS BEEN  
INSPECTED IN ACCORDANCE WITH A 100hr/Annual/  
INSPECTION AND WAS DETERMINED TO BE IN  
AIRWORTHY CONDITION. TOTAL TIME 101.0**

**W.O. 13992 DATE 9-3-97**

**INSPECTOR G. D. J. G.  
RAYTHEON AIRCRAFT SERVICES  
REPAIR STATION XA1R605K**

**HOBBY AIRPORT  
HOUSTON, TEXAS**

# MAINTENANCE & SERVICE HISTORY

Reg: N1113H-- Prop.

Date: 2/19/98

WorkOrder: 14807

Mod: Beech A36

HourMeter: 199.3

S N: E-3081

TotalTime: 199.3

Raytheon Aircraft Services, Inc.

Propeller Total Time: 199.3 hours

Complied with Annual/100 Inspection.

Complied with STARS:

611031: Inspect electric prop. deice system-- Not installed.

I Certify that this Propeller has been inspected in accordance with an Annual/100 hour Inspection and was determined to be in airworthy condition.

Mark Currie  
Raytheon Aircraft Services, Inc.

FAA Repair Station XA1R605K

Houston, TX 77061

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12			

# MAINTENANCE & SERVICE HISTORY

D:	DATE: 04/26/01	REG: C-FMMC	S/N: E-3081	WO: 40353	PAGE 1 OF 1
		AFTT: 523.2	HOBBS: 523.2	PROP: D3A32C409C	S/N: 962436
				TSN: 523.2	TSO:
				DATE OF OVHL:	

ES  
ON  
S

## INSPECTIONS:

1. PERFORMED ANNUAL INSPECTION I/A/W BEECHCRAFT BONANZA 33, 35 & 36 100 HOUR OR ANNUAL LONG FORM INSPECTION GUIDE P/N 98-32227H.

ALL AIRWORTHINESS DIRECTIVES THRU BI-WEEKLY 01-07 HAVE BEEN VERIFIED FOR COMPLIANCE.  
I certify that this PROPELLER has been inspected in accordance with inspections and procedures for an inspection program required by FAR 91.409 (a)(1) and has been found to be in airworthy condition and is approved for return to service. Pertinent details are on file at this repair station under work order # 40353 dated 04/26/01.

Authorized Signature

INSPECTION: ANNUAL

RAYTHEON AIRCRAFT SERVICES, INC. CRS# VG4R595M  
2450 N. WESTSHORE BLVD. TAMPA, FL. 33607

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

# MAINTENANCE & SERVICE HISTORY

Make: McCauley  
Model: D3A32C409-C  
Serial No.: 962436



**Teledyne Continental Motors, Inc.**  
A Teledyne Technologies Company

Date: 03/22/2002  
Hobbs Time: 773.0  
Total Time: 773.0

TCM Customer Support Center, 8600 County Rd 32, Fairhope, AL 36532 FAA Repair Station No. ID4R254M

The work performed as described below has been inspected in accordance with current regulations of the Federal Aviation Administration and found to be in airworthy condition.

**Work Performed:** This propeller was installed on Raytheon A36 Bonanza, S/N E-3081, N256DB with new o'ring and torqued to specifications. Completed ground operational checks, leak check and flight check. **---END---**

Authorized Signature: Michael C. Lindsay Details of the work performed is on file under Work Order No. 1459


NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

# MAINTENANCE & SERVICE HISTORY

Make: McCauley  
Model: D3A32C409-C  
Serial No.: 962436



Date: 05/07/2002  
Hobbs Time: 846.8  
Total Time: 846.8

TCM Mattituck Service Center, 8600 County Rd 32, Fairhope, AL 36532 FAA Repair Station No. ID4R254M

I certify that this airframe, engine, propeller has been inspected in accordance with an **annual** inspection and determined to be in airworthy condition.

**Work Performed:** Completed an **ANNUAL** inspection in accordance with Beechcraft Bonanza 100 Hour or Annual Long Form Inspection Guide 98-32227H. Dynamically balanced propeller to 0.09 ips. Completed a ground operational check and leak check. ----END----

Authorized Signature: Michael C. Lindsay Details of the work performed is on file under Work Order No. 1502


NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

# MAINTENANCE & SERVICE HISTORY



**Hangar One, Inc.**

625 Regional Airport Rd.  
Carrollton, Ga. 30117  
FAA#KHNRA53Y



atures  
Station  
nbers

WORK ORDER # SE-103

MODEL: 5-36

SN# E308C

PROP TL: 1185.5

DATE: 06/13/2013

A/C REG# N2565B

HORDE: 1185.5

## L COMPLETED ANNUAL INSPECTION IN ACCORDANCE WITH BLUICRAFT'S 300 HR INSPECTION GUIDE

I certify that this aircraft/component was inspected in accordance with Beech maintenance manual and the current FAK's and was determined to be in an airworthy condition and is approved for return to service. Pertinent details are on file under work order.  
Signature: John L. Lippincott Jr.

2013


**NOTE: Enter Compliance with All Applicable F.A.A. A.D. & Factory Service Bulletins On Pages 11 & 12**

# MAINTENANCE & SERVICE HISTORY



**Hangar One, Inc.**

635 Regional Airport Rd.  
Carrollton, Ga. 30117  
FAACRS#R1NR453Y



**WORK ORDER #:** SH-1539

**MODEL:** D3A32C409C

**S/N #:** 962436

**PROP TT :** 1542

**DATE:** 7-1-04

**A/C REG #:** N256DB

**HOBBS:** 1542

---

**1. PERFORMED ANNUAL INSPECTION IAW BEECH SHOP MANUAL INSPECTION INSTRUCTIONS,**

I certify that this aircraft/component was inspected/repaired IAW Beech maintenance manual and the current FAR's and was determined to be in an airworthy condition and is approved for return for service. Pertinent details are on file under work order.  
Signature Gary Hampton

END

**NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12**

