

**HARTZELL**

# PROPELLER LOGBOOK

PROPELLER MODEL PHC-J3Y/F-1N

PROPELLER S/N NJ18808


LOGBOOK # 1

Description of all operations per IAW  
Service Documents, Overhaul, Major or Minor Repair, and Inspect

A/C  
Hrs

0.0

I have Dynamically Balanced Propeller IAW Hartzell  
Propeller Owner's Manual 145 Rev. 18 dated Nov/17  
Section: 61-00-45 on 12-20-2018 (DATE).  
The location of the Weight(s) are none degree  
And are none gram(s).



(Sign/Stamp)

Cirrus Design Corporation,

PC 338CE

wo: WO\_2089

Propeller Annual - page 1 of 1



Sierra Aero LLC - 10356 Truckee Airport Rd, Hangar #1 - Truckee, CA 96161 - 530-359-8751

N119BK  
Tach: 195.4


HARTZELL, PHC-J3Y1F-1N, S/N: NJ1880B  
Hobbs: 256.7 TSN: 256.7

January 14, 2020

1. Performed annual inspection per Sierra Aero LLC Inspection Check List, ref. Cirrus AMM, Chapter 05-20. Visually inspected propeller blades, hub and spinner, no discrepancies noted. Lubricated per AMM.

I certify that this PROPELLER has been inspected IAW an ANNUAL inspection and found airworthy on this date. -END- Details of work performed are on file with Sierra Aero LLC under work order: WO\_2089.

Taylor Good IA 3529105





Sierra Aero LLC - 10356 Truckee Airport Rd, Hangar #1 - Truckee, CA 96161 - 530-359-8751

**N119BK**      **HARTZELL, PHC-J3Y1F-1N, S/N: NJ1880B**  
 Flight Hobbs: 267.2      hobbs: 353.4

February 1, 2021

TSN: 353.4

1. Performed annual inspection per Sierra Aero LLC Inspection Check List, ref. Cirrus AMM, Chapter 05-20. Visually inspected propeller blades, hub and spinner, no discrepancies noted. Lubricated per AMM.

I certify that this PROPELLER has been inspected IAW an ANNUAL inspection and found airworthy on this date. -END- Details of work performed are on file with Sierra Aero LLC under work order: WO\_2668.

Taylor Good IA 3529105

PROP MODEL  
PHC-J3Y1F-1N  
PROP S/N NJ1880B  
REG NO N119BK  
WORK ORDER  
TKI1387-01-2022

### CIRRUS Cirrus Design Factory Service Center

Repair Station No YD5R855Y  
4961 Airport Road  
Duluth, MN 55811  
Phone 218-788-3049


DATE 2/11/2022  
A/C TSN 357 2  
PROP TT 357 2  
TSPOH  
HOBBS 466 1

### Prop Entries

(7) Performed an annual inspection of this propeller in accordance with Cirrus Aircraft SR-22T AMM 05-20 inspection checklist.  
 (21) Inspected propeller and propeller spinner IAW CDC SR22T AMM 61-10. No discrepancies or evidence of oil leakage found.  
 (46) I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in an airworthy condition.

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of this work order are on file at this Certified Repair Station CRS YD5R855Y

DATE: 2/11/2022

SIGNED: 

Jaryd Martin  
Certified Repair Station No YD5R855Y

Work Order: TKI1387-01-2022

Printed by EBis 3 (datcomedia.com)

Propeller TSN	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
------------------	------------	--

PROP MODEL PHC-J3Y1F-1N  
PROP S/N NJ1880B  
REG NO N119BK  
WORK ORDER ISM10224-01-2023



**CIRRUS** Cirrus Factory Service Center

4134 Aviation Drive  
Kissimmee, FL 34741

DATE 2/7/2023  
A/C TSN 429 7  
PROP TT 429 7  
TSPOH  
FLIGHTTIME 429 7

### Prop Entries

(6) Performed an annual inspection of this propeller in accordance with Cirrus Aircraft SR-22T AMM 05-20 inspection checklist.  
(37) I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in an airworthy condition.

DATE: 2/7/2023

SIGNED:

Work Order: ISM10224-01-2023

Israel Lopez Ramos, IA 3629553

Printed by EBis 3 (datcomedia.com)

PROP MODEL PHC-J3Y1F-1N  
PROP S/N NJ1880B  
REG NO N119BK  
WORK ORDER ISM10734-01-2024



**CIRRUS** Cirrus Factory Service Center

Repair Station No 9B0D988C  
4134 Aviation Drive  
Kissimmee, FL 34741  
Phone 689-244-5221

DATE 2/1/2024  
A/C TSN 511 6  
PROP TT 511 6  
TSPOH  
FLIGHTTIME 511 6

### Prop Entries

(6) Performed an annual inspection of this propeller in accordance with Cirrus Aircraft SR-22T AMM 05-20 inspection checklist.  
(55) I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in an airworthy condition.

The aircraft, airframe, aircraft engine, propeller or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of this work order are on file at this Certified Repair Station CRS 9B0D988C

DATE 2/1/2024

SIGNED:

Work Order: ISM10734-01-2024

Israel Lopez Ramos  
Certified Repair Station No 9B0D988C

Printed by EBis 3 (datcomedia.com)

MAKE: Cirrus  
MODEL: SR22T  
S/N: 1853  
REG. NO: N119BK  
PROP MODEL: PHC-J3Y1F-1N  
PROP 1 SN: NJ1880B



**Cirrus Factory Service Center**  
Repair Station No. 9B0D988C  
4134 Aviation Drive  
Kissimmee, FL 34741

W/O #: ISM12525-02-2025  
DATE: 03-06-2025


### Propeller entries

6 Performed an annual inspection of this propeller in accordance with Cirrus Aircraft SR-22T AMM 05-20 inspection checklist.  
59 I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in an airworthy condition.

The aircraft, airframe, aircraft engine, propeller or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of this work order are on file at this Certified Repair Station CRS 9B0D988C.

DATE: 03-06-2025

SIGNED:

  
Israel Lopez Ramos  
Repair Station No. 9B0D988C

WORK ORDER: ISM12525-02-2025

Printed by EBIS (EBISCloud.com)