

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL 94C-33Y1F-1N/17605

PROPELLER S/N 15299B

LOGBOOK # 1

PROPELLER MAINTENANCE RECORD

Position one

PITCH RANGE

Propeller Model PHC-J3YIF-11V/N7605

High/Feather _____

Propeller S/N NJ299B

Start Lock _____

Blade Design N7605

Low _____

Blade S/N's

Reverse _____

No. 1 A3978

No. 2 A3980

Aircraft Manufacturer Cirrus

No. 3 A3983

Aircraft Model SR22

No. 4 _____

S/N 3681

No. 5 _____

Registration N531CC

No. 6 _____

Spinner Assembly Part No. _____

Service Documents, Overhaul, Major or Minor Repair and Inspection

Date	Propeller		A/C Hrs
	TSN	TSO	

North East Aero

97 Hangar RD Montgomery NY, 12549 (845) 457-1184

Cirrus Design SR22 N531CC S/N 3681

Hobbs Time: 198.3

Air Hobbs: 123.5

S/N: NJ299B

24, October 2012

Hartzell PHC-J3YF-1N

1. Completed Annual Inspection IAW Cirrus Design 100hr/Annual Inspection checklist.
2. Lubricated propeller as required.
3. Dressed blades as required.
4. Completed AD search and complied with all outstanding AD's as required. Reference AD list dated 10/12.

*I certify this Propeller was inspected in accordance with
an Annual Inspection and found to be in an airworthy condition.*

James T. Markey 31668721A

North East Aero

97 Hangar RD Montgomery NY, 12549 (845) 457-1184

Cirrus Design SR22 N531CC S/N 3681

Hobbs Time: 256.1

Air Hobbs: 163.2

S/N: NJ299B

01, October 2013

Hartzell PHC-J3YF-1N

1. Completed Annual Inspection IAW Cirrus Design 100hr/Annual Inspection checklist.
2. Lubricated propeller as required.
3. Dressed blades as required.
4. Completed AD search and complied with all outstanding AD's as required. Reference AD list dated 10/13.

*I certify this Propeller was inspected in accordance with
an Annual Inspection and found to be in an airworthy condition.*

James T. Markey 31668721A

