

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-J3Y1F-1N

PROPELLER S/N NJ619B

LOGBOOK # _____

PROPELLER MAINTENANCE RECORD

Position ONE

PITCH RANGE

Propeller Model PHC-J3YIF-1N

High/Feather _____

Propeller S/N NJ619B

Start Lock _____

Blade Design N 7605B

Low _____

Blade S/N's

Reverse _____

No. 1 A5960

No. 2 A5957

Aircraft Manufacturer Cirrus Design Corp

No. 3 A5959

Aircraft Model SR22T

No. 4 _____

S/N 0363

No. 5 _____

Registration N 722NG

No. 6 _____

Spinner Assembly Part No. _____

Make: Hartzell
Model: PHC-J3YF-1N
Serial No.: NJ619B



Date: 2/18/2013
Flight Time: 190.4
Total Time: 190.4

FACTORY SERVICE CENTER

Continental Motors Factory Service Center, 8600 County Road 32, Fairhope, AL 36532 251-990-5080 FAA Repair Station No. 9CER853B

The work performed as described below has been inspected in accordance with current regulations of the Federal Aviation Administration and found to be in airworthy condition.

Work Performed: Performed 100 and 200 Hour Interval Items (In-Service Inspection II) of Cirrus Maintenance Program for Model SR22 and SR22T. Lubricated propeller hub. Completed ground operational checks. ---END---

Authorized Signature for Repair Station 9CER853B: Kenneth May
Details of the work performed are on file under Work Order No. 5410

Make: Hartzell
Model: PHC-J3YF-1N
Serial No.: NJ619B



Date: 6/4/2013
Flight Time: 300.8
Total Time: 300.8

FACTORY SERVICE CENTER

Continental Motors Factory Service Center, 8600 County Road 32, Fairhope, AL 36532 251-990-5080 FAA Repair Station No. 9CER853B

The work performed as described below has been inspected in accordance with current regulations of the Federal Aviation Administration and found to be in airworthy condition.

Work Performed: Performed 100 and 300 Hour Interval Items of Cirrus Maintenance Program for Model SR22 and SR22T. Lubricated propeller. Completed ground operational checks. ---END---

Authorized Signature for Repair Station 9CER853B: Douglas Budick
Details of the work performed are on file under Work Order No. 5545

Make: Hartzell
Model: PHC-J3YF-1N
Serial No.: NJ619B



Date: 1/9/2014
Flight Time: 444.0
Total Time: 444.0

FACTORY SERVICE CENTER

Continental Motors Factory Service Center, 8600 County Road 32, Fairhope, AL 36532 251-990-5080 FAA Repair Station No. 9CER853B

The work performed as described below has been inspected in accordance with current regulations of the Federal Aviation Administration and found to be in airworthy condition.

Work Performed: Performed 100 Hour Interval Items (In-Service Inspection) of Cirrus Maintenance Program for Model SR22 and SR22T. Lubricated propeller hub. Completed ground operational checks. ---END---

Authorized Signature for Repair Station 9CER853B: _____
Details of the work performed is on file under Work Order No. 5660

A handwritten signature in black ink that reads "Kenneth W. May".

Make: Hartzell
Model: PHC-J3YF-1N
Serial No.: NJ619B



Date: 8/13/2014
Flight Time: 596.3
Total Time: 596.3

FACTORY SERVICE CENTER

Continental Motors Factory Service Center, 8600 County Road 32, Fairhope, AL 36532 251-990-5080 FAA Repair Station No. 9CER853B


I certify that this propeller has been inspected in accordance with an **annual** inspection and determined to be in airworthy condition.

Work Performed: Completed an **ANNUAL** inspection in accordance with the scope and detail of the items listed in **14 CFR 43 Appendix D** using the Cirrus Models SR22 and SR22T Airplane Maintenance Manual Scheduled (Annual/100 Hour) Inspection Report and Cirrus Warranty Maintenance Program Checklist as a guide (50, 100, 200, 300 Hour and 2 year interval items). Lubricated propeller hub. Completed ground operational checks. ---END---

Authorized Signature for Repair Station 9CER853B:

A handwritten signature in cursive script that reads "Douglas Budick".

Details of the work performed is on file under Work Order No. 5942

Date	Propeller TSN TSO		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
Make: Hartzell Model: PHC-J3YF-1N Serial No.: NJ619B				Date: 6/17/2015 Flight Time: 801.3 Total Time: 801.3
 CONTINENTAL MOTORS SERVICES				
Continental Motors Services, 8600 County Road 32, Fairhope, AL 36532 251-990-5080 FAA Repair Station No. 9CER853B				
The work performed as described below has been inspected in accordance with current regulations of the Federal Aviation Administration and found to be in airworthy condition with respect to the work performed.				
Work Performed: Performed 100 Hour Interval Items (In-Service Inspection) and lubrication of Cirrus Maintenance Program for Model SR22 and SR22T. Completed ground operational checks. ---END---				
Authorized Signature for Repair Station 9CER853B: <u><i>Kenneth May</i></u> Details of the work performed is on file under Work Order No. 6223				

Make: Hartzell
Model: PHC-J3YF-1N
Serial No.: NJ619B



Date: 9/22/2015
Flight Time: 836.0
Total Time: 836.0

CONTINENTAL MOTORS SERVICES

Continental Motors Services, 8600 County Road 32, Fairhope, AL 36532 251-990-5080 FAA Repair Station No. 9CER853B

I certify that this propeller has been inspected in accordance with an annual/100 hour inspection and determined to be in airworthy condition.

Work Performed: Completed an ANNUAL inspection in accordance with the scope and detail of the items listed in 14 CFR 43 Appendix D using the Cirrus Models SR22 and SR22T Airplane Maintenance Manual Scheduled (Annual/100 Hour) Inspection Report as a guide. Lubricated propeller. Completed ground operational and leak check. ---END---

Authorized Signature for Repair Station 9CER853B: Kenneth May

Details of the work performed is on file under Work Order No. 6274
