

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-J3YF-1N

PROPELLER S/N FP2681B

LOGBOOK # 1

THIS SERVICE RECORD shall accompany the propeller equipment at all times. When equipment is installed as part of an Aircraft or engine, this record shall be maintained concurrently with and become a part of the Aircraft and Engine Service Records.

PROPELLER MAINTENANCE RECORD

Position Front

PITCH RANGE

Propeller Model PHC-J3YF-1N

High/Feather 35.0

Propeller S/N FP7681B

Start Lock N/A

Blade Design N7605B

Low 12.2

Blade S/N's

Reverse N/A

No. 1 A4505

Aircraft Manufacturer Cirrus

No. 2 A4513

Aircraft Model SR22

No. 3 A4515

S/N 979



No. 4 _____



Registration N509CE

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
			<p>TORNADO ALLEY TURBO INC. 300 AIRPORT RD ADA, OK 74820 N509CE CIRRUS SR22-G2 SN: 979 ACFT HOBBS: 2119.8 FLIGHT: 2119.8 HARTZELL PHC-J3YF-1N/N7605B SN: FP7681B PROP TSN: 0.0 INSTALLED THIS NEW PROPELLER ON THIS DATE AND THESE AIRCRAFT HOURS. INSTALLATION COMPLETED IN ACCORDANCE WITH HARTZELL INSTALLATION INSTRUCTIONS AND COVERED UNDER CURRENT CIRRUS TYPE DATA CERTIFICATE. OPERATION RUN-UP AND LEAK CHECK GOOD.</p> <p><i>[Signature]</i> DAVID R. LANDRETH A&P 2651512 IA</p>
			<p>PROPELLER LOG BOOK ENTRY 21 APRIL 2011</p> <p style="text-align: right;">TORNADO ALLEY TURBO, INC. </p>
			<p>PROP MODEL: PHC-J3YF-1N PROP S/N: FP7681B REG. NO: N509CE WORK ORDER: 28958-02-2012</p> <p> Commander Aero, Inc. 10570 Springboro Pike Miamisburg, Ohio 45342 USA Phone: 888-881-5580</p> <p style="text-align: right;">DATE: 3/16/2012 A/C TSN: 2225.3 PROP TT: 105.5 HOBBS: 2225.3</p> <p>Prop Entries (4) Complied with 100 Hour Propeller Inspection.</p> <p>I certify that this aircraft was inspected in accordance with an annual inspection and found to be airworthy. The aircraft and/or component(s) on N509CE was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 28958-02-2012.</p> <p>DATE: 3/16/2012 SIGNED: <i>[Signature]</i> Work Order: 28958-02-2012 Printed by EBis 3 (datcomedia.com)</p>

			<p>PROP MODEL: PHC-J3YF-1N PROP S/N: FP7681B REG. NO: N509CE WORK ORDER: 29303-03-2013</p> <p> Commander Aero, Inc. Repair Station No. GA5R-876M 10570 Springboro Pike Miamisburg, Ohio 45342 USA Phone: 888-881-5580</p> <p style="text-align: right;">DATE: 4/10/2013 A/C TSN: 2336 PROP TT: 266.2 HOBBS: 2336</p> <p>Prop Entries (4) Complied with 100 HR service items and annual inspection of Propeller. Lubricated with Aeroshell 6.</p> <p>I certify that this aircraft was inspected in accordance with an annual inspection and found to be airworthy. The aircraft and/or component(s) on N509CE was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 29303-03-2013.</p> <p>DATE: 4/10/2013 SIGNED: <i>[Signature]</i> Work Order: 29303-03-2013 Minzler, Alvin Certified Repair Station No. GA5R-876M Printed by EBis 3 (datcomedia.com)</p>
			<p>PROP MODEL: PHC-J3YF-1N PROP S/N: FP7681B REG. NO: N509CE WORK ORDER: 29655-05-2014</p> <p> Commander Aero, Inc. Repair Station No. GA5R-876M 10570 Springboro Pike Miamisburg, Ohio 45342 USA Phone: 888-881-5580</p> <p style="text-align: right;">DATE: 7/11/2014 A/C TSN: 2535 PROP TT: 415.2 HOBBS: 2535</p> <p>Prop Entries (4) Complied with 100 Hour Propeller Inspection.</p> <p>I certify that this aircraft was inspected in accordance with an annual inspection and found to be airworthy. The aircraft and/or component(s) on N509CE was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 29655-05-2014.</p> <p>DATE: 7/11/2014 SIGNED: <i>[Signature]</i> Work Order: 29655-05-2014 Minzler, Alvin Certified Repair Station No. GA5R-876M Printed by EBis 3 (datcomedia.com)</p>

