

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-J3YF-1RF/F7694

PROPELLER S/N F12400B

LOGBOOK # _____

PROPELLER MAINTENANCE RECORD

Position _____

PITCH RANGE

Propeller Model QHC-534E-1RF/F7694

High/Feather _____

Propeller S/N FP2400B

Start Lock _____

Blade Design 3 Blade

Low _____

Blade S/N's

Reverse _____

No. 1 589541

No. 2 589542

No. 3 589544

No. 4 _____

No. 5 _____

No. 6 _____

Aircraft Manufacturer Cirrus

Aircraft Model SR22

S/N 0637

Registration _____

Spinner Assembly Part No. _____

PROP MODEL:
PHC-J3YF-1RF/F7694
PROP S/N FP2400B
REG NO 6019Q
WORK ORDER:
1344-05-2004



Cirrus Design Factory Service Center

Repair Station No. YD5R855Y
4515 Taylor Circle
Duluth, MN 55811
Phone: 218- 788-3101

DATE 6/11/2004
A/C TSN
PROP TT 436 1
TACH

Prop Entries

(6) Performed Propeller 100 HR inspection IAW AMM ch 5-20 ... (9) Researched ADs through bi-weekly issue 2004-10, all ADs are in compliance at this time. ... (43) Removed and replaced propeller slinger ring, fluid feed standoffs, and spinner bulkhead with new IAW AMM ch 61-10 ... (49) 61-10 Installed new spinner P/N 15176-002 S/N AI-0389 in accordance with CH61-10 ... (76) Dynamically balanced propeller IAW CDC AMM chap 61 ... (77) Dressed minor nicks and gouges from prop leading edges IAW AMM ch. 61-10 ... (84) 5-20 I certify that this propeller has been inspected in accordance with a 100HR inspection and was determined to be in airworthy condition.



AOA Maintenance LLC
319 N Crystal Lake Drive
Orlando Florida 32803



N6019Q
S/N 0637
MODEL: SR22

TACH: 657.4

Monday, 2 February, 2009

PROPELLER

COMPLIED WITH **ANNUAL INSPECTION** IAW FAR 43 APPENDIX D USING THE CIRRUS SR-22 100 HR CHECKLIST AS A GUIDE. REMOVED NICKS AND GOUGES FROM EDGES OF PROP BLADES. SERVICED PROP HUB WITH AEROSHELL #6 GREASE. ALL AD'S RESEARCHED THRU 2009-01.

I CERTIFY THAT THIS PROP WAS INSPECTED
IAW AN **ANNUAL** INSPECTION WAS FOUND IN AIRWORTHY
CONDITION AND RETURNED TO SERVICE.


CLIFF IVIE
IA 2844370



AOA Maintenance LLC
319 N Crystal Lake Drive
Orlando Florida 32803



N6019Q
S/N 0637
MODEL: SR22

TACH: 690.6

Wednesday, 17 March, 2010

PROPELLER

C/W ANNUAL INSPECTION IAW FAR 43.15(c) APPENDIX D USING THE CIRBUS SR-22
100 HR CHECKLIST AS A GUIDE. REMOVED NICKS AND GOUGES FROM EDGES OF PROP
BLADES. SERVICED PROP HUB WITH AEROSHELL #6 GREASE. ALL AD'S RESEARCHED
THRU 2010-05.

I CERTIFY THAT THIS PROP WAS INSPECTED
IAW AN ANNUAL INSPECTION WAS FOUND IN AIRWORTHY
CONDITION AND RETURNED TO SERVICE.

C. Wilson
CHARLES WILSON
IA3114515

PR
CO
100
BLA
THE

I CERT
IAW AN
CONDIT