

N337TM
HARTZELL

N337TM #2
PROPELLER LOGBOOK

PROPELLER MODEL PHC-53Y1F-1M/N7605B

PROPELLER S/N MJ470B

LOGBOOK # _____

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		



HARTZELL SERVICE CENTER

One Propeller Place
Piqua, Ohio 45356 U.S.A

November 21, 2019

W/O:16456 S/N: **NJ470B** TSN: Not Provided TSO: 0.0

Pertinent details of the work performed are specified on the provided FAA
Form 8130-3, Tracking Number MK40430, Dated 21 Nov 2019.

Paul Schiml Repairman #
Repair Station # SJ3R843L

DATE 2/07/2020

STEEL AVIATION INC
Prop LOG

N337TM
TACH 1312.2
MAKE Cirrus

S/N 2216
Hobbs 1533.9
Model SR22T

1.C/W 100HOUR/ANNUAL INSPECTION in accordance with FAR 43
APENDDIX D, Using Cirrus AMM as a guide.

TSN:1312.2

TSO:0

I certify that this prop has been inspected in accordance
with (annual) inspection and was determined to be in
airworthy condition.

A/P 2796210291/A Richard Booze


