


The Standard

PROPELLER LOG

ASA-SP-L



The Standard

PROPELLER LOG

ASA-SP-L

Propeller Record General Information

Propeller Manufacturer MT - Propeller

Model MTV - 14 - D

Hub Series # 110587

Date of Manufacture 11/08/2011

Type _____

Blade # ACE - 43034

ACE - 43035

ACE - 43036

ACE - 43037

Make/Model

Serial #

Aircraft Installed On: CIRRUS SR22

1946

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year	Total Time	Description
------	------------	-------------

Date PROP MODEL:
MTV-14-D/195-30B
Next Due: PROP S/N: 110587
REG. NO: N44WW
WORK ORDER: 26010



Legend Aviation LLC
2020 Clubhouse Drive
Prescott, AZ 86301
Phone: 928.717.1680

DATE: 5/29/2019
A/C TSN: 1663.6
PROP TT: 736.7
TSPOH:
HOBBS: 1663.6

Prop Entries

- (3) Complied with and Annual inspection in ref. to Cirrus MM P/N:13773-001 Rev.B8 and Annual/100hr. inspection checklist. All A.D.'s current through Biweekly issue 2019-11.
- (15) Installed correct hardware stack up on prop governor.IAW Cirrus IPC 76-10-04.
- (16) Installed safety wire to Pro Governor adjustment screw.

Next Due: Technicians Who Worked On The Items Listed Above:
Bill Samuelson, Chris Kahl

I certify this propeller has been inspected I.A.W. a 100 hr./Annual inspection and has been determined to be in airworthy condition at this time.

The aircraft propeller identified above was repaired and inspected in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair are on file at this agency.

Year DATE: 5/29/2019 SIGNED: *Bill Samuelson* Work Order: 26010
Date Bill Samuelson, IA: 27471961A Printed by EBis 3 (datcomedia.com)

Next inspection Due:	Time Since Overhaul	Mech. Cert. # or Repair Station #
-----------------------------	----------------------------	--

PROP MODEL:
MTV-14-D/195-30B
PROP S/N: 110587
REG. NO: N44WW
WORK ORDER: 26209



Legend Aviation LLC

2020 Clubhouse Drive
Prescott, AZ 86301
Phone: 928.717.1680

DATE: 6/11/2020
A/C TSN: 1722.7
PROP TT: 795.8
TSPOH:
HOBBS: 1722.7

NOTATIONS

Prop Entries

(3) Complied with and Annual inspection IAW FAR 43 Appendix(d) using Legend Aviations Annual / 100Hr. inspection checklist and manufactures maintenance manuals. Inspected Prop hub, blades, spinner, and bulkhead. All applicable AD'S complied with.

I certify that this propeller has been inspected in accordance with the above inspection and was determined to be in airworthy condition.

The aircraft propeller identified above was repaired and inspected in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair are on file at this agency.

DATE: 6/11/2020

SIGNED:

Work Order: 26209

David P. Anderson, IA: 3119079

Printed by EBis 3 (datcomedia.com)

Next Inspection Due:	Time Since Overhaul	Mech. Cert. # or Repair Station #
-----------------------------	----------------------------	--

Year:	Total Time in Service	Description
--------------	------------------------------	--------------------

Next Inspection Due:	Time Since Overhaul	Mech. Cert. # or Repair Station #
-----------------------------	----------------------------	--