


Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		

wo: WO_562 Propeller - page 1 of 1




Steel Aviation · 53 North Street Ext · Phillipsburg, Ohio 45354 · 937 332 7587

N647MD HOBBS: 1094.1	Hartzell, PHC-J3YF-1RF, S/N: FP5374B TACH: 876.1	November 27, 2024
--------------------------------	--	--------------------------

1. C/W Annual Inspection in accordance with FAR 43 Appendix D - using Hartzell manual 115N as a guide .
2. Lubricated propeller hub with Aeroshell 6.

I certify that this Propeller has been inspected in accordance with an (annual) inspection and was determined to be in airworthy condition. Details of work performed are on file with Steel Aviation under work order: WO_562.

Jeff Pleiman A/P I/A 3304319 



- Madison, WI 608-268-5003 Dane County Regional Airport (MSN)
- Watertown, WI 920-261-4567 Watertown Municipal Airport (RYV)
- Juneau, WI 920-386-2402 Dodge County Airport (UNU)

Date: 11/21/2025; Aircraft: N647MD; Type: CIRRUS SR20; S/N: 1772; Hobbs: 933.6; Total Time: 933.6; Engine - Type: IO-360-ES6, S/N: 360319, Time: 933.6; Prop - Type: PHC-J3YF-1RF, S/N: FP5374B, Time: 933.6
 Propeller

Completed an Annual inspection in accordance with FAR 43, Appendix D. Performed ground run, operational, and leak checks - no defects noted. All work performed in accordance with approved/current technical data. I certify that this propeller has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition.

Doug Seibel
 A&P389765035 IA 