

Page No. **4**

Maine Aviation

Aircraft Maintenance, LLC.

406 Yellowbird Road • Portland International Airport • Portland, ME 04102
(207) 780-1811 • Fax (207) 772-6900

CRS FSER011E

| Date | WO# | Registration | Type/Model | SN | ACTT | Propeller TSN |
|----------|-------|--------------|-------------|-------|-------|---------------|
| 11/19/12 | 36046 | N611RJ | HC-H3YF-1RF | LX58B | 782.6 | 782.6 |

Inspected iaw Cessna Model 400 Annual Inspection Guide
Dressed all three blades.
Engine run up—all ground checks satisfactory, no leaks noted.

I certify that this Propeller has been inspected in accordance with an **Annual Inspection**, and was determined to be in airworthy condition. All applicable AD Notes have been complied with and this propeller is approved for return to service.

Signature: [Signature]
MAINE AVIATION AIRCRAFT MAINTENANCE, L.L.C., PORTLAND, MAINE
REPAIR STATION FSER011E

Maine Aviation

Aircraft Maintenance, LLC.

406 Yellowbird Road • Portland International Airport • Portland, ME 04102
(207) 780-1811 • Fax (207) 772-6900

CRS FSER011E

| Date | WO# | Registration | Type/Model | SN | ACTT | Propeller TSN |
|----------|-------|--------------|-------------|-------|-------|---------------|
| 12-09-13 | 37328 | N611RJ | HC-H3YF-1RF | LX58B | 849.3 | 849.3 |

Inspected iaw Cessna Model 400 Annual Inspection Guide
Engine run up—all ground checks satisfactory, no leaks noted.

I certify that this Propeller has been inspected in accordance with an **Annual Inspection**, and was determined to be in airworthy condition. All applicable AD Notes have been complied with and this propeller is approved for return to service.

Signature: [Signature]
MAINE AVIATION AIRCRAFT MAINTENANCE, L.L.C., PORTLAND, MAINE
REPAIR STATION FSER011E

Maine Aviation

Aircraft Maintenance, LLC.

406 Yellowbird Road • Portland International Airport • Portland, ME 04102
(207) 780-1811 • Fax (207) 772-6900

CRS FSER011E

| Date | WO# | Registration | Type/Model | SN | ACTT | Propeller TSN |
|----------|-------|--------------|-------------|-------|-------|---------------|
| 12-29-14 | 38280 | N611RJ | HC-H3YF-1RF | LX58B | 933.2 | 933.2 |

Inspected iaw Cessna Model 400 Annual Inspection Guide
Engine run up—all ground checks satisfactory, no leaks noted.

I certify that this Propeller has been inspected in accordance with an **Annual Inspection**, and was determined to be in airworthy condition. All applicable AD Notes have been complied with and this propeller is approved for return to service.

Signature: [Signature]
MAINE AVIATION AIRCRAFT MAINTENANCE, L.L.C., PORTLAND, MAINE
REPAIR STATION FSER011E

| | | | | | | |
|---|--|--|--|--|--|--|
| SUB-TOTALS this page | | | | | | |
| TOTALS —Carry forward to next page | | | | | | |