N4311W



Propeller Record	General Information	1			
Propeller Manufacture	er Hartzel	(			
lodel HC-F	2YR-IRF			Type	
lub Series #C	M793				
ate of Manufacture			_		
			-		
				-	
- +	Make/Model			Serial #	
ircraft Installed On:		· · · · · · · · · · · · · · · · · · ·			
					21.00
	Manufacture of the Control of the Co				

l	Total Time in Service	Description	the second secon
	1 .	l	the second second second second
AUC	GUSTA A	VIATION, INC.	•
1775	EL FIELD (DI HIGHLAND A	WÉ.	"Excellence Since 1940"
AUG	USTA, GA 30	904	
			Augusta Aviati
Date 3176			
Perfo		been inspected in accord	dance with the 100 Hour Inspection, FARs and applicable manufactures and is
Perfo		2 20 20	dance with the 100 Hour Inspection, FARs and applicable manufacturer specifications
Perfo	ify this Prop has determined to be	2 20 20	dance with the 100 Hour Inspection, FARs and applicable manufacturer specifications
Perfo	ify this Prop has determined to be	2 20 20	dance with the 100 Hour Inspection, FARs and applicable manufacturer specifications

A STATE OF STREET	in Service	Description	
Dates			
A 1 1	LICTA AVA	ATION INC	
		ATION, INC. "Excellence Since 1940"	
	L FIELD (DNL) HIGHLAND AVI		
	STA, GA 3090		igusta Aviation, Inc.
AUGU	31A, GA 3030		
		- 11244141 T DADG DDG CAL DG 9311024: Tach: 3 1: Total Time: 3176.3: Prop - T	ype: , S/N:, Time:
Date:	11/20/2009: Aircra	11. N4371W: TVDE: PAZ8-Z30; 3/N. 20-0311024, Tacit, 3.1, Total Tille, 0170.0; Top	
Date: 3176.	11/20/2009; Aircra 3, SMOH: 105.5	ift; N4311W; Type; PA28-236; S/N: 28-8311024; Tach: 3.1; Total Time; 3176.3; Prop - Ty	
3176.	3, SMOH: 105.5		
3176. Perfo	3, SMOH: 105.5 rmed Annual Prop	Inspection.	
3176. Perfo	3, SMOH: 105.5 rmed Annual Prop to this Prop has be	Inspection.  en inspected in accordance with the Annual Inspection, FARs and applicable manufactu	
3176. Perfo	3, SMOH: 105.5 rmed Annual Prop to this Prop has be		
3176. Perfo	3, SMOH: 105.5 rmed Annual Prop to this Prop has be	Inspection.  en inspected in accordance with the Annual Inspection, FARs and applicable manufactu	
3176. Perfo	3, SMOH: 105.5 rmed Annual Prop to this Prop has be	Inspection.  en inspected in accordance with the Annual Inspection, FARs and applicable manufactu	
3176. Perfor I certi was d	3, SMOH: 105.5 rmed Annual Prop to this Prop has be	Inspection.  en inspected in accordance with the Annual Inspection, FARs and applicable manufactu	
3176. Perfor I certi was d	3, SMOH: 105.5 rmed Annual Prop fy this Prop has be letermined to be in	Inspection.  en inspected in accordance with the Annual Inspection, FARs and applicable manufactu	

HUB & BLADE INSPECTIONS	REPAIRS AND ALTERATIONS
-------------------------	-------------------------

## AUGUSTA AVIATION, INC.

DANIEL FIELD (DNL) 1775 HIGHLAND AVE. AUGUSTA, GA 30904

"Excellence Since 1940"



Date: 10/14/2010; Aircraft: N4311W; Type: PA28-236; S/N: 28-8311024; Tach: 10.2; Total Time: 3183.4; Prop - Type: , S/N:, Time: 3183.4, SMOH: 112.6

Performed Annual Prop inspection as required. No defects noted at this time.(1) AD 09-22-03, Propeller Hub Front Cylinder Half, D/N/A due to engine model.(6)(5)(6)(5)

I certify this Prop has been inspected in accordance with the Annual Inspection, FARs and applicable manufacturer specifications and was determined to be in airworthy condition.

IA 256217253

Overhaul

Mech. Cert. # or Repair Station #

Dressed	light nicks	Hartzell HC-F2YR-1RF Tach Time: 150.1 TSMOH 252.5 on propeller. Greased propeller as per Hartzell owner's manual.	IS [
	nat this pro been found	peller has been inspected in accordance with a 100 hour inspection to be in an airworthy condition at this time.	
y Joshua L		2861559AP	
Next Inspection Due:	Time Since Overhaul		
		Mech. Cert. # or Repair Station #	
Year:	Total Time in Service	Description	
Date:			
Next Inspection Due:	Time Since Overhaul		
		Mech. Cert. # or Repair Station #	

## Achievement Aviation LLC

Facility Address: Van Wert County Airport 1400 Leeson Ave Van Wert, OH 45891 Mailing Address: P.O. Box 1036 Van Wert, OH 45891 Phone# (260) 525-2975

December 5, 2012 N4311W PA28-236 SN#28-8311024 Tach Time: 201.9 Hartzell HC-F2YR-1RF TSMOH:304.3

Checked propeller blades for nicks, cracks and leakage. Lubricated propeller with Aeroshell #6 as per service manual.

Checked AD listing - none applicable at this time.

I certify that this PROPELLER has been inspected in accordance with an ANNUAL inspection in accordance with 14CFR43 Appendix D and was determined to be in an airworthy condition at this time.

Joshua L Johnson

Ne

Da — Ne

Da

AP 2861559IA

## **Achievement Aviation LLC**

Facility Address: Van Wert County Airport 1400 Leeson Ave

Van Wert, OH 45891

June 7. 2014 N4311W Hartzell HC-F2YR-1RF T

Tach Time: 220.0

Mailing Address: PO Box 1031 Van Wert, OH 45891 Phone# (260) 525-2975

Total Time: 3393.2 Propeller Time

SMOH: 322.4

(1) Performed annual inspection of propeller, spinner & backplate by use of checklist conforming to 14CFR43 Appendix D

(2) Lubricated propeller with Aeroshell #6

Checked status of airworthiness directives through biweekly supplement 2014-10. See separate listing this date for details. No AD's due at this time

I certify that this PROPELLER has been inspected in accordance with an ANNUAL inspection and was found to be in airworthy condition.

Joshua L Johnson

A&P 2861559 IA

meun. vert. # or nepair station #

	Achievement Aviation LLC							
Year	Facility Address: Mailing Address:							
Date	Van Wert County Airport PO Box 1031							
Next	1400 Leeson Ave Van Wert, OH 45891							
Due:	Van Wert, OH 45891 Phone# (260) 525-2975							
	July 6, 2015 N4311W Hartzell HC-F2YR-1RF Tach Time: 250.4 Total Time: 3423.6 Propeller Time							
	SMOH: 352.8							
Year:	(1) Performed annual inspection of propeller, spinner & backplate by use of checklist conforming to							
Date:	14CFR43 Appendix D							
-	(2) Lubricated propeller with Aeroshell #6							
Next Due:	(3) Repaired nick in face of propeller blade & repainted face of blade as per Hartzell manual 115N section 61-00-15.							
	01-00-10.							
	Checked status of airworthiness directives through biweekly supplement 2015-12. See separate listing this							
	date for details. No AD's due at this time							
Year:								
Date:	I certify that this PROPELER has been inspected in accordance with an ANNUAL inspection and was found to							
Next	be in airworthy condition.							
Due:	Joshua L Johnson A&P 2861559 IA							
	000110011							
-1								

And the state of the state of the

Achievement Aviation LLC	] S □	
Facility Address: Lakefield Airport 6177 St Rd 219 Celína, OH 45822		
August 16, 2016 N4311W Hartzell HC-F2YR-1RF SN# CM-793 Tach Time: 280.0 Total Time: 3453.2 SMOH: 382.4		
<ol> <li>Performed annual inspection of propeller in accordance with 14 CFR 43 Appendix D</li> <li>Lubricated propeller in accordance with Hartzell manual 115N section 6-5.</li> <li>Checked airworthiness directives through biweekly supplement 2016-14. None due at this time. See separate listing for details.</li> </ol>		
I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition  Joshua L Johnson  2861559 A&P IA		