

#3

Propeller Logbook



SENSENICH PROPELLER SERVICE, INC.

McCauley

Hartzell

MT

Sensenich

Dowty

Hamilton Standard

INSTALLING AGENCY PLEASE NOTE:
Recording of Propeller Total Time Since New (TTSN)
is Required Per F.A.R. 91.417

962436

Lancaster Airport, 519 East Airport Road, Lititz, PA 17543 (800) 462-3412 (717) 560-3711 Fax: (717) 560-4354 FAA Certified Repair Station #QV9R194N

Lee Gilmore Memorial Airport, 1142 Aviation Boulevard, Gainesville, GA 30501 (800) 791-7767 (770) 538-0444 Fax: (770) 538-0117 FAA Certified Repair Station #S46R346N

Windham County Airport, 21 Airport Road, North Windham, CT 06256 (877) 456-7944 (860) 456-7944 Fax: (860) 456-0410 FAA Certified Repair Station #Q0PR011X

SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures
3/1/13	2372.9	- 0 -	OVERHAULED/MAJOR INSPECTED BY SENENICH PROPELLER SERVICE, INC.	
			Hub Serial No. <u>962436</u>	
			Blade Ser. No. <u>QI 032</u>	
			<u>QI 100</u>	
			<u>QI 112</u>	
			Blade Angles Low <u>13.7</u> High <u>28.8</u>	
			Rev. <u>—</u> Feather <u>—</u>	
		<u>300-0-</u>	<u>W.O. L24984 TSN.</u>	<u>2372.9</u>
<p>Complied with AD 2007-08-04 AS Pkr ASB 248 BLADES AND HUB LIFE LIMITED TO 10,000 Hours, INSPECTION REQUIRE AT ANNUAL OR 100 Hours</p>				
<p><i>C. May Hulse</i> Sensenich Propeller Service Repair Station #QV9R194N</p>				


SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures
PROPS MODEL PROP S/N REG NO 256DB WORK ORDER 10089	 <p>Lincoln Park Aviation 425 Beaverbrook Road Lincoln Park, NJ 07035 Phone: 973-633-0450</p>		DATE 3/22/2013 A/C TSN 2373 1 PROP TT 612 8 HOBBS 2373 1	
<p>Prop Entries (3) ANNUAL/PROP - PROPELLER OVERHAULED BY SENENICH UNDER WORK ORDER # L24984</p> <p>The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below</p> <p>DATE 3/22/2013 SIGNED  Frank R Galella, IA 2764795</p> <p>Work Order 10089 Printed by EBis 3 (datcomedia.com)</p>				
PROPS MODEL PROP S/N REG NO 256DB WORK ORDER 10470	 <p>Lincoln Park Aviation 425 Beaverbrook Road Lincoln Park, NJ 07035 Phone: 973-633-0450</p>		DATE 4/2/2014 A/C TSN 2462 4 PROP TT 2462 4 HOBBS. 2462 4 <i>89.3 Smo k</i>	
<p>Prop Entries (3) 100HR/ANNUAL/PROP - INSPECTED PROPELLER IN ACCORDANCE WITH 100/ANNUAL INSPECTION (5) COMPLIED WITH AD 2007-08-04 PROP INSPECTION LIFE LIMIT PLACARD INSPECTION, IAAW McCUALEY ASB 248</p> <p>The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below</p> <p>DATE 4/2/2014 SIGNED  Frank R Galella, IA 2764795</p> <p>IA#2764795 Work Order 10470 Printed by EBis 3 (datcomedia.com)</p>				

SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures
	PROP MODEL: PROP S/N: REG. NO: 256DB WORK ORDER: 10858	 Lincoln Park Aviation 425 Beaverbrook Road Lincoln Park, NJ 07035 Phone: 973-633-0450	DATE: 4/13/2015 A/C TSN: 2546.4 PROP TT: 2546.4 HOBBS: 2546.4	
	Prop Entries (3) 100HR/ANNUAL/PROP - INSPECTED PROPELLER IN ACCORDANCE WITH 100/ANNUAL INSPECTION			
	The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below.			
	DATE: 4/13/2015	SIGNED: 	Work Order: 10858	
		Frank R. Galella, IA: 2764795	Printed by EBis 3 (datcomedia.com)	
	PROP MODEL: PROP S/N: REG. NO: 256DB WORK ORDER: 11214	 Lincoln Park Aviation 425 Beaverbrook Road Lincoln Park, NJ 07035 Phone: 973-633-0450	DATE: 4/27/2016 A/C TSN: 2668.6 PROP TT: 2668.6 HOBBS: 2668.6	
	Prop Entries (3) 100HR/ANNUAL/PROP - INSPECTED PROPELLER IN ACCORDANCE WITH 100/ANNUAL INSPECTION			
	The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below.			
	DATE: 4/27/2016	SIGNED: 	Work Order: 11214	
		Frank R. Galella, IA: 2764795	Printed by EBis 3 (datcomedia.com)	

SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures
	PROP MODEL: PROP S/N: REG NO 256DB WORK ORDER 11526	 Lincoln Park Aviation 425 Beaverbrook Road Lincoln Park, NJ 07035 Phone: 973-633-0450	L	DATE 4/3/2017 A/C TSN 2782 2 PROP TT 2782.2 HOBBS 2782.2
	Prop Entries (3) 100HR/ANNUAL/PROP - INSPECTED PROPELLER IN ACCORDANCE WITH 100/ANNUAL INSPECTION			
	The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below			
	DATE: 4/3/2017	SIGNED:  Frank R. Galella IA# 2764795	CRS# LKPR101K	Work Order: 11526
				Printed by EBis 3 (datcomedia.com)
	PROP MODEL: PROP S/N: REG NO 256DB WORK ORDER 11880	 Lincoln Park Aviation 425 Beaverbrook Road Lincoln Park, NJ 07035 Phone 973-633-0450		DATE: 4/16/2018 A/C TSN 2915 PROP TT 2915 HOBBS 2915
	Prop Entries (3) 100HR/ANNUAL/PROP - INSPECTED PROPELLER IN ACCORDANCE WITH 100/ANNUAL INSPECTION (5) COMPLIED WITH AD 2007-08-04, BY INSPECTION OF REQUIRED PANEL PLACARD AND INSPECTION PER MCCAULEY ASB248 BLADES AND HUB LIFE LIMITED TO 10,000 HOURS TOTAL PROP TIME 2915 0 ACTT NEXT INSPECTION DUE AT 3115 0 ACTT OR 3/2019			
	The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below			
	DATE: 4/16/2018	SIGNED:  Frank R. Galella IA# 2764795	IA#2764795	Work Order: 11880
				Printed by EBis 3 (datcomedia.com)

SERVICE HISTORY

D PROP MODEL:
PROP S/N:
REG. NO: 256DB
WORK ORDER: 12186



Lincoln Park Aviation
425 Beaverbrook Road
Lincoln Park, NJ 07035
Phone: 973-633-0450

DATE: 5/13/2019
A/C TSN: 3056.5
PROP TT: 3056.5
HOBBS: 3056.5

Prop Entries

(3) 100HR/ANNUAL/PROP - INSPECTED PROPELLER IN ACCORDANCE WITH 100/ANNUAL INSPECTION

The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below.

DATE: 5/13/2019

SIGNED:

Frank R Galella, IA: 2764795

Work Order: 12186

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PROP S/N:
REG. NO: 256DB
WORK ORDER: 12435



Lincoln Park Aviation
425 Beaverbrook Road
Lincoln Park, NJ 07035
Phone: 973-633-0450

DATE: 4/27/2020
A/C TSN: 3196.6
PROP TT: 3196.6
TACH: 3196.6

Prop Entries

(3) 100HR/ANNUAL/PROP - INSPECTED PROPELLER IN ACCORDANCE WITH 100/ANNUAL INSPECTION... (5) COMPLIED WITH AD 2007-08-04, INSPECTION OF REQUIRED PANEL PLACARD AND INSPECTION AS PER MCCUALEY ASB248. TOTAL PROPELLER TIME 3196.6 ACTT HOURS, NEXT DUE 3296.6 HOURS OR 04/2020.

The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Particular details of the repair are on file at this repair station under work order listed below.

DATE: 4/27/2020

SIGNED:

Frank R Galella, JA: 2764795

Work Order: 12435

Printed by EBis 3 (datcomedia.com)



Printed by EBIS 3 (datcomedia.com)

PROP MODEL:
PROP S/N:
REG. NO 256DB
WORK ORDER 12722



Lincoln Park Aviation
425 Beaverbrook Road
Lincoln Park, NJ 07035
Phone 973-633-0450

DATE 4/22/2021
A/C TSN 3259
PROP TT 0
TACH 3259

Date

Prop Entries

(3) 100HR/ANNUAL/PROP - INSPECTED PROPELLER IN ACCORDANCE WITH 100/ANNUAL INSPECTION... (13) REMOVED AND REPLACED PROPELLER WITH NEW MT PROPELLER, P/N: MTV-9-D, S/N: 201109.

The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below.

DATE: 4/22/2021

SIGNED:

Frank R Galella, IA 2764795

A handwritten signature in blue ink, appearing to read 'Frank R Galella', is written over the signature line and the identification number 'IA#2764795'.

Work Order: 12722

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PROP S/N:
REG. NO: 256DB
WORK ORDER: 13029



Lincoln Park Aviation
425 Beaverbrook Road
Lincoln Park, NJ 07035
Phone: 973-633-0450

DATE: 5/19/2022
A/C TSN 3422 2
PROP TT: 163.2
TSPOH 163.2
TACH: 3422.2

Prop Entries

(3) 100HR/ANNUAL/PROP - INSPECTED PROPELLER IN ACCORDANCE WITH 100/ANNUAL INSPECTION

The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below.

DATE: 5/19/2022

SIGNED:

Frank R Galella, IA 2764795

A handwritten signature in blue ink, appearing to read 'Frank R Galella', is written over the signature line and the identification number 'IA#2764795'.

Work Order: 13029

Printed by EBis 3 (datcomedia.com)

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
10/15 2022	00:00	—	Manufactured	 
7/29/22	0.0	—	Installed BFG-37572 de-ice boots IAW MT-Propeller Overhaul Manual E-1290 Rev 46. Reassembled propeller without spinner and torqued only check nuts and safety wired, IAW MT-Propeller Overhaul Manual E-220, Rev 68. Tim Paine A# P2756905	

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

MAINTENANCE & SERVICE HISTORY

TACH 3441.2 HOURS

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
10/22	Ø	Ø	Install This Propeller on N256DB. 7777	2764795

PROP MODEL
PROP S/N.
REG NO 256DB
WORK ORDER 13318



Lincoln Park Aviation
425 Beaverbrook Road
Lincoln Park NJ 07035
Phone 973-633-0450

DATE 8/7/2023
A/C TSN 3540 3
PROP TT 99 1
TACH 3540 3

Prop Entries

(3) 100HR/ANNUAL/PROP - INSPECTED PROPELLER IN ACCORDANCE WITH 100/ANNUAL INSPECTION

The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below

NC

DATE: 8/7/2023

SIGNED:

Frank R Galella, IA/2764795

IA#2764795

Work Order: 13318

1 & 12

Printed by EBis 3 (datcommedia.com)

PROP MODEL:
PROP S/N:
REG. NO. 256DB
WORK ORDER 13564



Lincoln Park Aviation

425 Beaverbrook Road
Lincoln Park, NJ 07035
Phone: 973-633-0450

DATE: 7/11/2024
A/C TSN 3659.1
PROP TT 217 9
TACH. 3659.1

Prop Entries

(3) 100HR/ANNUAL/PROP - INSPECTED PROPELLER IN ACCORDANCE WITH 100/ANNUAL INSPECTION

The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below.

DATE: 7/11/2024

SIGNED:

Frank R Galella, IA 276479

Work Order: 13564

Printed by EBis 3 (datcomedia.com)

MAINTENANCE & SERVICE HISTORY

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12